

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO 1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SJX 3368A Policy No. D22MTPV01001527 Coverage (\$) 0.00 Claim No. CMTD2204325/THE Excess (\$) 0.00		
SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO 1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SJX 3368A Veh. Inspected SLR 7189 Policy No. D22MTPV01001527 Coverage (\$) 0.00		
1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SJX 3368A Veh. Inspected SLR 7189 Policy No. D22MTPV01001527 Coverage (\$) 0.00	G	
Insured Veh. SJX 3368A Veh. Inspected SLR 7189 Policy No. D22MTPV01001527 Coverage (\$) 0.00	nG	
Policy No. D22MTPV01001527 Coverage (\$) 0.00	ig l	
Claim No. CMTD220/325/THE Excess (\$) 0.00		
Ciaiii 140. GWI DZZO45Z5/TILE EXCESS (\$)		
Assign From GRACE TEO Assign Date 29/11/202	.2	
2. Vehicle Particulars & Condition		
Make & Model MAZDA 6 c.c 1998		
Engine No. HIDDEN Year of Reg. 2017		
Chassis No. JM6GL1071H0117622 Colour BRONZE		
Odometer 63103 KM Steering IN ORDE	R	
Brakes IN ORDER Modification SPORTS	RIM	
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre 215/55 R17 RAPID 6 mm		
L/H Front Tyre 215/55 R17 RAPID 6 mm		
R/H Rear Tyre 215/55 R17 RAPID 6 mm		
L/H Rear Tyre 215/55 R17 RAPID 6 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.		
DAMAGES SEE DETAILS.		
5. General Information		
Accident Date 27/11/2022 Inspection Date 29/11/202	.2	
Survey held at SM AUTOMOTIVE		
BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days		