

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 Blk C #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241

Fax: (65) 6741 7276

RCB No: 53231488C GST Reg No : 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date : 27/11/2022

29/11/2022

Estimated repair cost for vehicle no: SLR7189G MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT

CHASSIS: JM6GL1071H0117622 (2017)

S/N	Qty	Items	U/price	Amount
1	1	REAR BUMPER <i>Debond.</i>	✓	
2	2	REAR BUMPER REFLECTOR <i>Not new</i>	X	
3	2	REAR BUMPER TOWING COVER <i>Missing.</i>	✓	
4	2	REAR BUMPER RETAINER <i>New</i>	✓	
5	1	REAR BUMPER REINFORCEMENT ?	?	
6	2	REAR BUMPER BRACKET ?	?	
7	1	REAR BUMPER UNDER COVER <i>Not new.</i>	X	
8	4	REAR BUMPER REVERSE SENSOR <i>2 pieces damaged</i>	1/2	
9	4	REAR BUMPER REVERSE SENSOR BRACKET <i>New</i>	✓	
10	1	REAR BOOTLID <i>Buckled</i>	✓	
11	1	REAR BOOTLID LOCK <i>Damaged</i>	✓	
12	1	REAR BOOTLID EMBLEM LOGO <i>2</i>	✓	
13	1	REAR BOOTLID EMBLEM MAZDA 6 <i>New</i>	✓	
14	1	REAR BOOTLID EMBLEM SKYACTIVE <i>New</i>	✓	
15	1	REAR BOOTLID WEATHER STRIPE <i>cut</i>	✓	
16	2	REAR TAILLAMP ?	?	
17	1	REAR END PANEL ?	?	
18	1	REAR END PANEL TOP GARNISH <i>?</i>	?	
19	1	REAR EXHAUST MUFFLER <i>Ryix</i>	X	
20	1	REAR EXHAUST MUFFLER SHIELD ?	?	
21	1	FRONT BUMPER <i>Debond</i>	✓	
22	1	FRONT BUMPER REINFORCEMENT ?	?	
23	1	FRONT BUMPER LOWER GRILLE <i>Not new</i>	X	
24	1	FRONT BUMPER TOP GARNISH ?	?	
25	1	FRONT GRILLE <i>Crushed</i>	✓	
26	1	FRONT GRILLE SIDE CHROME <i>cut</i>	✓	
27	1	FRONT GRILLE LOGO <i>New</i>	✓	
28	1	FRONT HEADLAMP LH ?	?	
29	1	FRONT HEADLAMP LOWER BRACKET LH ?	?	

SLR7189G MAZDA 6

TOTAL : \$0.00
 LESS 20 % \$0.00
 SUB-TOTAL : \$0.00

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	REAR BUMPER CLIPS <i>New</i>	\$80.00	\$80.00 <i>30</i>
2	1	REAR END PANEL TOP GARNISH CLIPS <i>?</i>	\$60.00	\$60.00 <i>?</i>
3	1	REAR NUMBER PLATE WITH CASING <i>xt new</i>	\$60.00	\$60.00 <i>x</i>
4	2	REAR TAILLAMP CLIPS <i>?</i>	\$8.50	\$17.00 <i>?</i>
5	1	REAR END PANEL SEALANT <i>?</i>	\$80.00	\$80.00 <i>?</i>
6	1	FRONT NUMBER PLATE WITH CASING <i>Best</i>	\$60.00	\$60.00 <i>✓</i>
7	1	FRONT BUMPER CLIPS <i>xt new</i>	\$80.00	\$80.00 <i>30</i>

TOTAL: \$437.00

TOTAL PARTS: \$437.00

Labour charges

1	LABOUR FOR PANEL BEATING	\$1,600.00 <i>?</i>
2	LABOUR FOR SPRAYPAINTING	\$1,200.00 <i>?</i>
3	WIRING CHECK	\$100.00 <i>60</i>
4	TO APPLY RUST PROOF / TUFF COATING ON ACCIDENT AREAS	\$300.00 <i>?</i>
5	LABOUR FOR REMOVE & TRANSFER REAR BOOTLID FITTING	\$150.00 <i>60</i>

Subtotal :- \$3,350.00

Total:- \$3,787.00

Admin LG
4/5 29/11/22
No of days : ??