

# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT  
AUTOWORK PTE LTD

DATE : 30.11.2022

TO : **SOMPO** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SLE7434S**  
MODEL : **VOLKSWAGEN GOLF**  
DATE OF ACCIDENT : 25.11.2022  
TIME OF ACCIDENT : 07:45 HOURS

www2224u2gw225877

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|--------------------------------------------|-----|-----------------|------------------|
| 1   | TAILGATE <i>dent</i>                       | 1   | \$ 2,169.10     | \$ 2,169.10      |
| 2   | TAILGATE EMBLEM 'GOLF' <i>new</i>          | 1   | \$ 110.03       | \$ 110.03        |
| 3   | TAILGATE WIPER ARM WITH BLADE <i>new</i>   | 1   | \$ 86.70        | \$ 86.70         |
| 4   | TAILGATE INNER TRIM <i>new</i>             | 1   | \$ 388.05       | \$ 388.05        |
| 5   | TAILGATE TOP LOCK <i>new</i>               | 1   | \$ 537.50       | \$ 537.50        |
| 6   | TAILGATE LOWER LOCK <i>new</i>             | 1   | \$ 40.75        | \$ 40.75         |
| 7   | TAILGATE LAMP <i>lt</i>                    | 2   | \$ 290.25       | \$ 580.50        |
| 8   | TAILGATE WEATHESTRIIP <i>new</i>           | 1   | \$ 378.16       | \$ 378.16        |
| 9   | TAIL LAMP <i>lt</i>                        | 2   | \$ 384.95       | \$ 769.90        |
| 10  | REAR BUMPER (UPPER) <i>dent</i>            | 1   | \$ 1,579.40     | \$ 1,579.40      |
| 11  | REAR BUMPER LOWER CENTER <i>dent</i>       | 1   | \$ 498.38       | \$ 498.38        |
| 12  | REAR BUMPER REFLECTOR <i>new</i>           | 2   | \$ 77.55        | \$ 155.10        |
| 13  | REAR BUMPER CENTER BRACKET <i>cracked</i>  | 1   | \$ 168.75       | \$ 168.75        |
| 14  | REAR BUMPER SIDE BRACKET <i>2 pc</i>       | 2   | \$ 54.55        | \$ 109.10        |
| 15  | REAR BUMPER SIDE BRACKET JOINT <i>2 pc</i> | 2   | \$ 78.45        | \$ 156.90        |
| 16  | REAR BUMPER REINFORCEMENT <i>dent</i>      | 1   | \$ 781.75       | \$ 781.75        |
| 17  | REAR NUMBER PLATE LAMP <i>2 pc</i>         | 2   | \$ 43.35        | \$ 86.70         |
| 18  | REAR FENDER INNER COWLING <i>2 pc</i>      | 2   | \$ 283.60       | \$ 567.20        |
| 19  | REAR END PANEL <i>Repair</i>               | 1   | \$ 937.53       | \$ 937.53        |
| 20  | REAR END PANEL TOP GARNISH <i>new</i>      | 1   | \$ 188.10       | \$ 188.10        |
| 21  | REAR FLOOR PANEL TOP BOARD <i>new</i>      | 1   | \$ 395.65       | \$ 395.65        |
| 22  | REAR WINDSCREEN <i>new</i>                 | 1   | \$ 1,316.80     | \$ 1,316.80      |
| 23  | REAR EXHAUST PIPE <i>2 pc</i>              | 1   | \$ 1,295.60     | \$ 1,295.60      |
| 24  | REAR EXHAUST MOUNTING <i>2 pc</i>          | 2   | \$ 55.10        | \$ 110.20        |
| 25  | REAR EXHAUST ISULATOR <i>1 pc</i>          | 1   | \$ 198.70       | \$ 198.70        |
| 26  | REAR RESERVE SENSOR <i>1 piece</i>         | 4   | \$ 236.50       | \$ 946.00        |

1795

1149

78.85

283.60

236.50

TO : **SOMPO** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **SLE7434S**  
 MODEL : **VOLKSWAGEN GOLF**  
 DATE OF ACCIDENT : 25.11.2022  
 TIME OF ACCIDENT : 07:45 HOURS

|    |                                 |   |          |          |
|----|---------------------------------|---|----------|----------|
| 27 | REVERSE SENSOR HOLDER <i>mm</i> | 1 | \$ 38.50 | \$ 38.50 |
|----|---------------------------------|---|----------|----------|

6490.36

5841.32

TOTAL PRICE \$ 14,591.05  
 LESS 10% \$ 1,459.11  
**SUB TOTAL PRICE \$ 13,131.95**

| S/N | DESCRIPTION                                               | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|-----------------------------------------------------------|-----|-------------|--------------|
| 1   | REAR NUMBER PLATE <i>Not nec</i>                          | 1   | \$ 80.00    | \$ 80.00     |
| 2   | REAR BUMPER CLIP (UPPER) (SET) <i>new</i>                 | 1   | \$ 30.00    | \$ 30.00     |
| 3   | REAR BUMPER LOWER CENTER CLIP (SET) <i>mm</i>             | 1   | \$ 50.00    | \$ 50.00     |
| 4   | TAIL GATE INNER TRIM BOARD CLIP (SET) <i>mm</i>           | 1   | \$ 50.00    | \$ 50.00     |
| 5   | TAILGATE WINDSCREEN SEALANT <i>gum</i>                    | 1   | \$ 80.00    | \$ 80.00     |
| 6   | TAILGATE WINDSCREEN INNER SEAL                            | 1   | \$ 60.00    | \$ 60.00     |
| 7   | TAILGATE WINDSCREEN SOLAR FILM <i>new</i>                 | 1   | \$ 200.00   | \$ 200.00    |
| 8   | TAILLAMP CLIP (SET) <i>new</i>                            | 1   | \$ 50.00    | \$ 50.00     |
| 9   | REAR FENDER INNER TRIM CLIP (SET) <i>new</i>              | 1   | \$ 50.00    | \$ 50.00     |
| 10  | REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>         | 1   | \$ 30.00    | \$ 30.00     |
| 11  | REAR END PANEL INSULATION SEAL                            | 1   | \$ 150.00   | \$ 150.00    |
| 12  | REAR SPOILER (SPECIAL TYPE) <i>Crushed</i>                | 1   | \$ 800.00   | \$ 800.00    |
| 13  | REAR EXHAUST CHROME PIPE <i>Not nec</i><br><i>Revised</i> | 2   | \$ 180.00   | \$ 360.00    |

**TOTAL \$ 1,990.00**

1150

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

| S/N | JOB DESCRIPTION                                                            | PRICE       | ADJUSTED COST |
|-----|----------------------------------------------------------------------------|-------------|---------------|
| 1   | TO PANEL BEAT, REMOVE AND REPLACE PARTS                                    | \$ 1,800.00 | 500           |
| 2   | TO SPRAY PAINT AFFECTED AREA                                               | \$ 1,400.00 | 500           |
| 3   | TUFF COAT                                                                  | \$ 250.00   | 30            |
| 4   | WIRING AND BULB CHECK                                                      | \$ 180.00   | 30            |
| 5   | REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR | \$ 150.00   | 30            |
| 6   | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                       | \$ 80.00    | 50            |
| 7   | REMOVE AND REFIX REAR SPOILER                                              | \$ 100.00   | 40            |
| 8   | TRANSFER TAILGATE MECHANISM                                                | \$ 80.00    | ✓             |

TO : **SOMPO** MOTOR CLAIMS DEPTS  
VEHICLE NO : **SLE7434S**  
MODEL : **VOLKSWAGEN GOLF**  
DATE OF ACCIDENT : 25.11.2022  
TIME OF ACCIDENT : 07:45 HOURS

|    |                                      |           |   |
|----|--------------------------------------|-----------|---|
| 9  | CONDUCT WATER LEAKAGE TEST           | \$ 80.00  | X |
| 10 | REMOVE AND REFIX REAR EXHAUST PIPE   | \$ 180.00 | X |
| 11 | REMOVE AND REFIX TAILGATE WINDSCREEN | \$ 120.00 | ✓ |
| 12 | REMOVE AND REFIX REAR WIRE HARNESS   | \$ 250.00 | X |

**TOTAL \$ 4,670.00**

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 15,121.95  
TOTAL LABOUR COST : \$ 4,670.00  
TOTAL REPAIR COST : \$ 19,791.95

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
IRENE  
HP : 8297 9787

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Adrian Lij  
N/S 30/11/22

04 Days

total: 8371.32

U/S: 6.7K