From: LKK Auto Consultants Pte Ltd

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

> 79 Robinson Road #09-01 Singapore 068897

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH 01 Dec 2022 Date:

Preliminary Advice

Vehicle No : SMM6871R Accident Date : 28/11/2022 Policy No. : SP2001964206 Make : TOYOTA COROLLA

Assignment Date : 29/11/2022 Excess : S\$0.00 Date of Inspection : 30/11/2022 Est. Duration of Repair : 8

Inspection At : BORNEO MOTORS (S) PTE LTD

2 PANDAN CRESCENT SINGAPORE 128462

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,009.38
Revised Amount	:S\$	17,475.24
Check Items (Estimated)	:S\$	5,225.30
Total	:S\$	22,700.54

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 94,000.00 COE / PARF Rebate :S\$ 34,807.00

Salvage Value :S\$

Margin for Repair :S\$ 59,193.00

Remarks

(x)	The vehicle is repairable at our adjuste	d amount. We	have also conf	firmed excess a	nd policy cov	erage. Kindly
	let us have your authorisation.					

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments :the vehicle repair on part by parts basis.due to the workshop is agent workshop. (x)Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.