

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 18 Jan 2023

## **Preliminary Advice**

Vehicle No	: SMM6871R	Accident Date	: 28/11/2022
Make	: TOYOTA COROLLA	Policy No.	: SP2001964206
Assignment Date	: 29/11/2022	Excess	: S\$0.00
Date of Inspection	: 30/11/2022	Est. Duration of Repair	: 8
Inspection At	: BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,173.58 (inclusive supp: \$164.20)
Revised Amount	:S\$	17,643.44
Check Items (Estimated)	:S\$	0.00
Total	:S\$	17,643.44
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	94,000.00
COE / PARF Rebate	:S\$	34,807.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,193.00

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Kindly approve on supplementary