



Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details		
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961			S1000040 / ALLIANZ		Mr Ng Joo Liang 51 Choa Chu Kang Loop #11-26 Singapore 689682 Mobile: 97398228		
			Document No. 0				
			Document Date 18/01/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ZRE171R	GEXGPZ S2	10/07/2019	SMM6871R	0	18850	72/OD/SMM6871R
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR053REH604598141		1ZR0D97694	60	Thomas Pang W T	02/12/2022 8.00		08/12/2022 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:sp2001964206 ACC DATE:28.11.2022 DRIVE IN:28.11.2022 EXCESS:NIL DATE-IN:02.12.2022 DATE SURVEY:30.11.2022 NO OF REPAIR DAYS:08 WORKING DAYS BY:LKK-RASUL AUTHORISED ON:01.12.2022				50.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00	
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP	*			134.64	
4	B	BP-LAB2 REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR	*			396.00	
5	B	BP-ECU2 TO RESET ECU AND REPROGRAMME		BP61		198.00	
6	B	BP-MECH2 TO CONDUCT FULL WHEEL ALIGNMENT		BP61		198.00	
7	S	BP-SUBLET REPLACE RIM AND WHEEL BALANCING		0239		158.40	
8	B	BP-LAB2 REPLACE ACC DAMAGED PARTS	*			2376.00	
9	B	BP-RES2 RESPRAY ACC AFFECTED AREAS	*			2624.00	
10	1	S52119-0Z982 COVER, FR BUMPER, L	1.00	576.20		576.20	
11	2	S52161-0K040 PIECE, RR BUMPER	10.00	4.50		45.00	
12	3	S52115-02380 SUPPORT, FR BUMPER S	1.00	73.70		73.70	
13	4	T90467-05170 CLIP	2.00	2.80		5.60	
14	5	T53879-58010 RETAINER, FR FENDER	2.00	9.40		18.80	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961			S1000040 / ALLIANZ		Mr Ng Joo Liang 51 Choa Chu Kang Loop #11-26 Singapore 689682 Mobile: 97398228			
			Document No.					
			0					
			Document Date					
			18/01/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	ZRE171R	GEXGPZ S2	10/07/2019	SMM6871R	0	18850	72/OD/SMM6871R	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053REH604598141		1ZR0D97694	60	Thomas Pang W T	02/12/2022 8.00		08/12/2022 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
15	6	S53801-02240 FENDER SUB-ASSY, FR			1.00	982.90		982.90
16	7	T90189-06013 GROMMET			10.00	2.70		27.00
17	8	S67001-02470 PANEL SUB-ASSY, DOOR			1.00	1359.30		1359.30
18	9	S75921-02220 TAPE, BLACK OUT, NO.			1.00	52.00		52.00
19	0	L90269-04051 RIVET			10.00	1.80		18.00
20	1	T90269-06013 RIVET			10.00	2.20		22.00
21	2	S75444-02700 PLATE, LUGGAGE COMPT			1.00	38.50		38.50
22	3	S81110-02N30 HEADLAMP ASSY, RH			1.00	4296.20		4296.20
23	4	S42611-02N20 WHEEL, DISC			1.00	2368.50		2368.50
24	5	S87910-02J20 MIRROR ASSY, OUTER R			1.00	1360.50		1360.50
25	6	S75710-02380 MOULDING ASSY, FR DO			1.00	164.20		164.20
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd							17,643.44	
			Please acknowledge receipt of vehicle				GST 7.00%	
					Parts 11,408.40		1,235.04	
					Labour 6,076.64			
					Sublet 158.40			
					Lubrication/Fluid 0.00		Less 0.00	
					Others 0.00		Amount Due 18,878.48	

Customer Copy