

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K
8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875



Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com

DATE : 29.11.22

TO : HL MOTOR CLAIMS DEPTS
VEHICLE NO : SNC8794H
MODEL : MERCEDES CLA180
DATE OF ACCIDENT : 27.11.22
TIME OF ACCIDENT : 13:00HRS

Xin Yu
WIK1183842N166101

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER Del'd	1	1924	\$ 1924 -
2	FRONT BUMPER LOGO New	1	105	\$ 105 -
3	FRONT BUMPER SIDE GRILLE LH Del'd	1	126	\$ 126 -
4	FRONT BUMPER SENSOR LH 1 piece damaged	2	235	\$ 470 -
5	FRONT BUMPER SENSOR HOLDER New	6	45	\$ 270 -
6	FRONT BUMPER CENTER BRACKET New	2	68	\$ 136 -
7	FRONT BUMPER UPPER BEAM New	1	192	\$ 192 -
8	FRONT BUMPER UPPER BEAM SIDE SUPPORT New	2	88	\$ 176 -
9	FRONT BUMPER SIDE RETAINER LH Del'd	1	145	\$ 145 -
10	FRONT BUMPER LOWER GRILLE New	1	385	\$ 385 -
11	FRONT BUMPER REINFORCEMENT New	1	568	\$ 568 -
12	FRONT BUMPER SPONGE Del'd	1	193	\$ 193 -
13	FRONT BUMPER BOTTOM COVER GARNISH New	1	388	\$ 388 -
14	FRONT HEADLAMP (LED) Del'd LH	2	3542	\$ 7084 -
15	FRONT HEADLAMP LOWER BRACKET SUPPORT LH New	1	98	\$ 98 -
16	FRONT GRILLE WITH CHROME Del'd	1	1682	\$ 1682 -
17	FRONT GRILLE SIDE AIR GUARD LH New	1	141	\$ 141 -
18	RADIATOR SUPPORT PANEL Del'd	1	820	\$ 820 -
19	RADIATOR AIR GUARD New	1	86	\$ 86 -
20	FRONT FENDER LH Buckled	1	886	\$ 886 -
21	FRONT FENDER COWLING (FRONT) LH Del'd	1	262	\$ 262 -
22	FRONT TURBO COOLER AIR GUARD New	1	198	\$ 198 -

9168
8251.20

TOTAL PRICE \$ -
LESS 10% \$ -
SUB TOTAL PRICE \$ -

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) New	1	\$ 120.00	\$ 120.00

TO : HL MOTOR CLAIMS DEPTS
 VEHICLE NO : SNC8794H
 MODEL : MERCEDES CLA180
 DATE OF ACCIDENT : 27.11.22
 TIME OF ACCIDENT : 13:00HRS

2	FRONT BUMPER SIDE GRILLE CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	20
3	FRONT BUMPER BOTTOM COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
4	FRONT NUMBER PLATE GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
5	FRONT FENDER COWLING CLIPS(SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
6	SUPPORT PANEL UNDER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
7	RADIATOR COOLANT <i>new</i>	1	\$ 180.00	\$ 180.00	50

130 TOTAL \$ 630.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	500
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	400
3	REFOCUS HEADLAMP BEAM	\$ 80.00	x
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	60
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	60
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	x

TOTAL \$ 2,830.00

TOTAL PARTS COST : \$ 630.00
 TOTAL LABOUR COST : \$ 2,830.00
 TOTAL REPAIR COST : \$ 3,460.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian G
1/8 29/11/22
05 days.

total: 9401.20

1/8: 7.5K.

7.5K