

KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

M (65) 9807 3304 Mr. Yap

F (65)

Email : kyautosg@gmail.com

Date: 28/11/2022

D.O.A 25/11/2022

SKR7744R Toyota Wish
Damaged Area: Front Left Side

→ SME654H

Parts / Material :

1	Front bumper	601	S	798.40 <i>de</i>
2	Front bumper reinforcement		S	355.90 x <i>nn</i>
3	Front bumper bracket n/s	50-30	S	68.90 <i>de</i>
4	Front bumper sponge		S	198.70 x <i>nn</i>
5	Front bumper side garnish n/s		S	195.20 x <i>nn</i>
6	Front bumper clips		S	55.00 <i>3000 SN</i>
7	Headlamp assy n/s	786	S	893.50 <i>aut</i>
8	Front fender n/s	698	S	786.90 <i>bt</i>
9	Front fender inner shield n/s	158	S	296.80 <i>de</i>
10	Front fender inner shield clips n/s		S	45.00 <i>rel-20SN</i>
11	Front fender quarter glass moulding n/s		S	298.70 x <i>nn</i>
12	Front fender lamp n/s		S	98.60 x <i>nn</i>
13	Wing mirror assy w/lamp n/s		S	495.80 <i>Ry</i>
14	Front door n/s		S	197.40 <i>Ry</i>
15	Front door upper hinge n/s		S	110.80 x
16	Front door lower hinge n/s		S	523.60 x
17	Front door inner trimboard clips		S	198.70 x
18	Rocker garnish n/s		S	145.30 x
19	Rocker garnish clips		S	235.70 x
20	Shock absorber n/s		S	430.20 x
21	Front lower arm n/s		S	495.80 x
22	Front knuckle arm n/s		S	565.80 <i>? bt</i>
23	Front steering ball joint n/s		S	155.70 x <i>nn</i>
24	Front knuckle hub bearing n/s		S	435.20 <i>? bt</i>
25	Front dri-shaft n/s		S	1,015.90 x <i>nn</i>
		2946.80		
		2210.10		
		SN 50		
			Parts : S	9,097.50
			Less Parts 25% : S	2,274.37
			Total Parts : \$	6,823.12

Special Net Items :

Front quarter glass scalant		S	80.00 <i>MM</i>
Front sport rim n/s		S	750.00 <i>aut-650</i>
Front tyre n/s		S	550.00 x <i>nn</i>
Front bumper lower spoiler		S	980.00 <i>aut-350</i>
		Total S/N Parts : \$	2,360.00

1000

Labour :

To Repair, Remove & Renew On Affected Accident Areas @ SGD 350.00 per day	S	1,100.00	600
To Putty, Spray Paint on Affected Accident Areas @ SGD 300.00 per panel	S	1,500.00	800
To Check & Re-Connect all electrical wiring	S	50.00	30
To Remove & Transfer Sport Rim & Tyre. To Conduct Tyre Balance	S	120.00	30
To Remove & Transfer Front Undercarriage Components to Facilitate Repairs	S	250.00	150? <i>uplink</i>
To Conduct Computerised Wheel Alignment	S	150.00	80
To Remove & Install Front Door Components To Facilitate Repairs	S	150.00	x <i>un</i>
To Conduct & Reset ECU Diagnostic Programme	S	450.00	x <i>un</i>
To Rust Proof Affected Areas	S	250.00	30
Total Labour :	\$	4,020.00	1720

TOTAL PARTS :	\$	6,823.12
TOTAL SPECIAL NET ITEM:	\$	2,360.00
TOTAL LABOUR :	\$	4,020.00
TOTAL REPAIR COST :	\$	<u>13,203.12</u>

22/10-10
50
1000
1720

Tanjin 9249544 498010
'wip' 20/11/22 @ 230pm 4/5 @ 4000
4/5 Resurvey after repair 4 days
Tanjin@lkhant.com
4 days
To check repair limit.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: