

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SFV911J

Make & Model: Nissan X-Trail

Chassis number: JN1JANT32Z0011414

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Front bumper	1	\$ de 594.10 ✓
2	Front bumper RH fog lamp	1	\$ × NN 258.90
3	Front bumper RH fog lamp cover	1	\$ × NN 87.80
4	Front bumper RH side retainer	1	\$ de 23.40 ✓
5	Front bumper LH side retainer	1	\$ × NN 23.40
6	RH headlamp assy	1	\$ cut 2,782.60 2642 ✓
7	Front grille emblem	1	\$ × NN 74.00
8	Front grille	1	\$ × NN 411.40
9	Front RH fender	1	\$ bt 641.70 ✓
10	Front RH fender splash shield	1	\$ × NN 132.60
11	Front RH fender arch moulding	1	\$ cut 189.20 ✓
12	Front RH sport rim	1	\$ cut 1,434.50 600 nett ✓
13	Front RH knuckle arm	1	\$ × NN 512.30
14	Front RH wheel bearing	1	\$ × NN 232.50
15	Front RH shock absorber	1	\$ × NN 378.40
16	Front RH shock absorber top mounting	1	\$ × NN 83.70
17	Front RH tie rod end	1	\$ × NN 127.60
18	Front RH door	1	\$ × NN 1,090.00
19	Front RH door frame black tape sticker	1	\$ × NN 32.00

4090.40

-10%

3681.36

600

Parts less 10% \$ 9,110.10

Total \$ 911.01

\$ 8,199.09

No.	Special Nett Items	Qty	Amount S\$
1	Front bumper clips	1set	\$ 30ne 80.00
2	Front RH fender splash shield clips	1set	\$ NN x 60.00
3	Front RH fender arch moulding clips	1set	\$ 20ne 70.00

50

Total: \$ 210.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall	\$ 1,200.00

	damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas		
2	Spray painting on affected areas and panels	\$ 500	1,000.00
3	Check wiring and lighting system on affected areas	\$ 30	60.00
4	Apply rust coating chemical on affected areas and panels	\$ 30	60.00
5	Refocus and adjust headlamps assy	\$ 30	80.00
6	Test drive and adjust wheel alignment system	\$ 80	180.00
7	Remove and replace front undercarriage parts to assist repair	\$ X	450.00
8	Remove and replace front RH door inner mechansim to new door	\$ X	150.00

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: _____

1070 Total: \$ 3,180.00

Spare Parts: \$ 8,199.09
Special Nett: \$ 210.00
Labour: \$ 3,180.00

Total Amount: \$ 11,589.09

Taufik 97445845

WP' 30/11/22 @ 430

L/S Resurvey after repair

fauzlin @ lkhunt.com

- To check consistency of accident.
- To check part prices

03 days

5401.36

L/S - 4321.08
= 4300

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (extra) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repa
Signature:
Date: