

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 22.30269 Date: 15<sup>th</sup> Feb 2023

Our Ref: CS3/ASM22001918/Tqp3e2-1

## M/s HSBC Life (Singapore) Pte Ltd

C/o Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBR 7685J

INSURED VEHICLE: SMM 1048J ACCIDENT DATE: 17/02/2022

We thank you for your instruction on 29/11/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBR 7685J from M/s Advanced Automotive Consultancy Pte Ltd.
- b) Survey report by Komoco Motors Pte Ltd with colour photographs.
- c) Singapore Accident Statement and Police Report of Vehicles FBR 7685J and SMM 1048J.
- d) Final Repair Bill of FBR 7685J from M/s EQBH Pte Ltd
- e) Colour damaged vehicle photographs of FBR 7685J.

Pre-Repair Inspection Date: 01/03/2022 at M/s Equator Brotherhood, 25 Kaki Bukit Road 4 #03-19 Synergy @KB, Singapore 417800.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : FBR 7685J

Make & Model : Yamaha Aerox GDR155A CVT ABS

Year of Registration : 2020

Chassis Number : MH3SG4640LJ072913

Engine Capacity : 155 cc

- 2. We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.