

Date : 17 FEB 2022

AXA Insurance (s) Pte Ltd

Attn: Motor Claims Department

Finalise

Vehicle number : **SMM 1048 J**
 Make and model : AVANTE 1.6 4DR AUTO "S"
 Registration Date : 18/06/2019
 Chassis number : KMHD841CMKU907588
 Engine number : G4FGKU143440

Job No. : 2022004130
 Owner name : Chan Ying Git
 Date of Acc : 17/2/2022
 Policy number : VPA/P2302946
 Claim Type : OD-Excess NIL

Items :		Estimate		Revised	
1	FRONT BUMPER CLIP X10	86595-2T500	\$ 12.00	\$ 12.00	
2	UPPER GRILLE CLIP X6	14206-08250B	\$ 3.60	\$ 3.60	
3	GRILLE ASSY-RADIATOR	86350-F2BA0	\$ 1,214.30	\$ 1,214.30	
4	COVER ASSY-RADIATOR GRILLE UPR	86360-F2AA0	\$ 84.50	\$ 84.50	
5	COVER-FR BUMPER	86511-F2AA0	\$ 498.20	\$ 498.20	
6	GRILLE-FRONT BUMPER SIDE,RH	86562-F2AA0	\$ 33.60	\$ 33.60	
7	BRACKET-FR BUMPER SIDE,RH	86514-F2AA0	\$ 13.70	\$ 13.70	
8	MOULDING-FRT BPR LICENSE PLATE	86519-F2AA0	\$ 17.40	\$ 17.40	
9	ABSORBER-FRONT BUMPER ENERGY	86520-F2AA0	\$ 110.70	\$ 110.70	
10	BRACKET ASSY-FR BUMPER UPR SUP	86555-F2AA0	\$ 10.60		Refit
11	BRACKET ASSY-FR BUMPER UPR SUP	86556-F2AA0	\$ 10.60	\$ 10.60	
12	DUCT ASSY-AIR CURTAIN,RH	86568-F2AA0	\$ 24.40	\$ 24.40	
13	STIFFNER-FR BPR LWR	86571-F2AA0	\$ 119.00	\$ 119.00	
14	MOULDING-FRONT BUMPER,LH	86563-F2AA0	\$ 103.80		Refit
15	MOULDING-FRONT BUMPER,RH	86564-F2AA0	\$ 103.80	\$ 103.80	
16	STRIP-FR BUMPER	86570-F2AA0	\$ 25.40		Refit
17	CAP ASSY-FR BPR	86588-F2AA0	\$ 7.80	\$ 7.80	
18	LIP ASSY-FRONT BUMPER	86591-F2AA0	\$ 71.70	\$ 71.70	
19	LAMP ASSY-FRONT TURN SIGNAL,RH	92302-F2500	\$ 164.80	\$ 164.80	
20	LAMP ASSY-HEAD,RH	92102-F2620	\$ 1,811.40	\$ 1,811.40	
21	WIRING ASSY-FEM	91875-F2080	\$ 112.00		Refit
22	CLIP-HEAD LAMP MTG X2	92173-F2000	\$ 4.00	\$ 4.00	
23	REINF ASSY-HEAD LAMP SUPT,RH	64128-F2000	\$ 25.10	\$ 25.10	
24	BEAM COMPLETE-FR BUMPER	64900-F2010	\$ 695.80	\$ 695.80	
25	CARRIER ASSY-FRONT END MODULE	64101-F2500	\$ 949.30	\$ 949.30	
26	PANEL ASSY-HOOD	66400-F2500	\$ 2,253.80	\$ 2,253.80	
27	HINGE ASSY-HOOD,LH	79110-F2000	\$ 49.10		Refit
28	HINGE ASSY-HOOD,RH	79120-F2000	\$ 49.10	\$ 49.10	
29	PANEL ASSY-FENDER,LH	66310-F2500	\$ 1,227.70		Refit

Vehicle number : **SMM 1048 J**
 Make and model : AVANTE 1.6 4DR AUTO "S"
 Registration Date : 18/06/2019
 Chassis number : KMHD841CMKU907588
 Engine number : G4FGKU143440

Job No. :2022004130
 Owner name : Chan Ying Git
 Date of Acc : 17/2/2022
 Policy number :VPA/P2302946
 Claim Type :OD-Excess NIL

Items :		Estimate	Revised
30	PANEL ASSY-FENDER,RH	66320-F2500 \$ 1,227.70	Refit
31	HORN ASSY-LOW PITCH	96610-F2100 \$ 78.30	Refit
32	MOTOR & PUMP-W/SHLD WASHER,FRT	98510-3T500 \$ 40.00	Refit
33	LEVEL SWITCH-WINDSHIELD WASHER	98521-F2000 \$ 28.00	Refit
34	RESERVOIR ASSY-W/SHLD WASHER	98620-F2510 \$ 57.50	Refit
35	HOSE	9J700-31047 \$ 28.80	Refit
36	GUARD ASSY-FRONT WHEEL,RH	86812-F2800 \$ 85.70	Refit
37	WHEEL GUARD CLIP X10	14206-08250B \$ 6.00	\$ 6.00
38	PANEL ASSY-UNDER COVER	29110-F2000 \$ 133.30	Refit
		\$ 11,492.50	\$ 8,284.60
Less 25% Discount		\$ 2,873.13	\$ 2,071.15
Material total		\$ 8,619.38	\$ 6,213.45

Body,Paint & Labour Items :		Estimate	Revised
1	To carry out accident body repair	\$ 2,240.00	\$ 1,280.00
2	Complete putty and spray paint all affected areas	\$ 1,960.00	\$ 840.00
Labour Charges:		Estimate	Revised
3	TO REFOCUS BOTH FRT HEAD LAMP (S.NETT)	\$ 40.00	\$ 40.00
4	TO SUPPLY BONNET SEALANT (S.NETT)	\$ 100.00	\$ 100.00
5	TO VACUUM & TOP UP AIRCON GAS (S.NETT)	\$ 140.00	None
6	TO SUPPLY & INSTALL FRT NUMBER PLATE (S.NETT)	\$ 40.00	\$ 40.00
7	TO REPAIR CHASSIS MEMBER (S.NETT)	\$ 320.00	None
8	TO PUT ON CHASSIS BENCH ALIGNER (S.NETT)	\$ 320.00	None
Total		\$ 13,779.38	\$ 8,513.45
Excess		\$ 13,779.38	\$ 8,513.45
Add GST 7%		\$ 964.56	\$ 595.94
Grand Total		\$ 14,743.93	\$ 9,109.39

*** Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out***