



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22011963/Awy3e2	
			Date: 20/06/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJT 4519X	Veh. Inspected	SMX 2924R	
Policy No.	D22MTPV01016834	Coverage (\$)	0.00	
Claim No.	CMTD2204326/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	29/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	NHP1707180972	Colour	BLACK	
Odometer	18670 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	HANKOOK	6 mm	
L/H Front Tyre	185/55 R15	HANKOOK	6 mm	
R/H Rear Tyre	185/55 R15	HANKOOK	6 mm	
L/H Rear Tyre	185/55 R15	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/11/2022	Inspection Date	29/11/2022	
Survey held at	UNIMOTOR COMPANY 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	