



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

XHP1707180972

TP Somp.

Xin Yu.

LKK

DATE: 22/12/2022 OUR REF: UAPL1570
REPAIR ESTIMATE TO THE TOYOTA SIENTA NO: SMX2924R

- 1 REAR BOOT ASSY *Damaged*
- 1 REAR BOOT LOCK *new*
- 1 REAR BOOT STRIKER *new*
- 2 REAR BOOT HINGES *new*
- 1 REAR BOOT FULL HANDLE *new*
- 1 REAR BOOT WEATHERSTRIP *new*
- 1 REAR BOOT INNER COVER LINING *new*
- 2 REAR BOOT STAY OPEN ABSORBER *new*
- 1 REAR BOOT OUTER GARNISH *new*
- 1 REAR BOOT KEY ANTENNA SENSOR *Damaged*
- 1 REAR BOOT TOYOTA LOGO *new*
- 2 REAR BOOT LAMP ASSY *new*
- 1 REAR BOOT GLASS MOULDING *new*
- 1 REAR BUMPER FACE *Damaged*
- 1 REAR BUMPER CENTRE GARNISH *Damaged*
- 2 REAR BUMPER SIDE COVER GARNISH *new*
- 2 REAR BUMPER SIDE RETAINER *new*
- 12 REAR BUMPER CLIPS *new*
- 1 REAR FENDER AIR DUCT *new*
- 1 REAR TAIL END PANEL (TOP) *new*
- 1 REAR TAIL END PANEL (LOWER) *new*
- 1 REAR PANEL LINING *new*

2501

1875.75

\$	1,350.00	1142
\$	285.00	
\$	34.00	
\$	98.00	
\$	28.00	
\$	296.00	
\$	233.00	
\$	520.00	
\$	288.00	
\$	185.00	
\$	65.00	
\$	640.00	
\$	224.00	148
\$	448.00	
\$	272.00	198
\$	320.00	
\$	160.00	
\$	60.00	30
\$	116.00	
\$	496.00	
\$	516.00	
\$	269.00	
\$	6,903.00	
\$	1,725.75	
\$	<u>5,177.25</u>	

LESS 25%.....

SPECIAL NETT:-

- 1 REAR NUMBER PLATE *new*
- 1 REAR REVERSE SENSOR *Damaged*

200

\$	50.00	
\$	200.00	200

LABOUR CHARGES:-

- TO SPRAY UNDERCOATING IN REPAIR
- TO DISM/REWIRE REAR DAMAGED PORTION
- TO DISM/REFIX REAR SEAT, ROOF LINING IN REPAIR
- TO DISM/REFIX REAR WINDSCREEN GLASS
- TO DISM/RENEW REAR REVERSE SENSOR
- TO PANEL BEAT DAMAGED CHASSIS FRAME PORTION & RENEW PARTS
- TO PUTTY AND RESPRAY DAMAGED PORTION

1380

\$	120.00	40
\$	200.00	30
\$	220.00	40
\$	160.00	120
\$	400.00	50
\$	4,000.00	500
\$	4,000.00	600
\$	<u>8,307.25</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3455.75

H/s: 2.7K ✓

04 Days