

GREEN FOREST AUTOMOBILE PTE LTD

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

DDMS PRODUCTION
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

Xin Yu.

ZWR800343364

Accident date:

Estimated repair cost for vehicle no: SML1883U TOYOTA NOAH 1.8 ' 2019

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dented</i>		\$1,774.20	✓
2	1	Rear Boot Lid HYBIRD logo <i>new</i>		\$40.00	✓
3	1	Rear Boot Lid lock <i>Damaged</i>		\$385.10	✓
4	1	Rear boot lid center moulding <i>cracked</i>		\$315.00	✓
5	6	Rear boot lid center moulding clips <i>new</i>	\$6.50	\$39.00	20. ✓
6	1	Rear Boot Lid weatherstrip <i>ht.</i>		\$285.00	✓
7	1	Rear boot lid emble logo <i>not in</i>		\$75.00	+
8	1	Rear Boot Lid Number Plate <i>green</i>		\$50.00	+
9	2	Rear Boot Lid Number Plate Lamp <i>green</i>	\$58.50	\$117.00	+
10	1	Rear boot lid inner rubber <i>not reported.</i>		\$265.00	+
11	1	Rear Boot Lid Inner Trim board <i>new</i>		\$552.10	+
12	1	Rear windscreen seal <i>new</i>		\$215.30	✓
13	2	boot lid side reflector <i>not in</i>	\$215.00	\$430.00	+
14	1	Rear Bumper <i>Damaged</i>		\$1,455.00	986
15	1	Rear bumper towing cover <i>not new</i>		\$68.00	+
16	2	Rear Bumper Side Reflector <i>green</i>	\$85.00	\$170.00	+
17	2	Rear Bumper Side Bracket <i>green</i>	\$155.00	\$310.00	+
18	2	rear bumper side retainer <i>new</i>	\$135.00	\$270.00	140
19	2	Rear bumper mud shield <i>not in</i>	\$155.00	\$310.00	+
20	8	Rear bumper clips <i>new</i>		\$50.00	30. ✓
21	1	Rear Bumper Reinforcement <i>not in</i>		\$658.00	+
22	1	Rear Bumper reverse sensor <i>not new</i>		\$350.00	+
23	1	Rear Boot Lid Inner Trim board handle <i>not new</i>		\$168.00	+
24	1	rear lower bumper <i>not in</i>		\$485.00	+
25	1	Antenna electrical key <i>cracked.</i>		\$425.00	146
26	1	end panel <i>Dented.</i>		\$783.20	✓
27	1	end panel top garnish <i>Damaged.</i>		\$258.20	✓
28	1	Rear spare tire panel top sponge <i>not new</i>		\$265.30	+
29	1	Rear spare tire panel top cover <i>cracked.</i>		\$485.20	✓
30	1	Rear spare tire panel sealant <i>new</i>		\$250.00	+

Front Bumper
Repair

1025

Subtotal :-

\$11,303.60

5863.20

4397.40.

Labour charges

To remove & re-fix cushion

\$120.00

60

to remove & Refix rear windscreen

\$120.00

✓

Gum

\$50.00

✓

to remove & Refix rear reverse sensor

\$120.00

50

To Check Wiring System

\$80.00

30

Tuff Kote

\$120.00

60

Panel beating

\$1400

1000

Spray painting

\$1400

1000

Subtotal :-

\$2,610.00

Total:-

\$13,913.60

Adrian Lj

h/s.

total: 6767.4.

h/s: S.H.K

06 Dec

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: