

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG22011970/KVY3E2  
**Date:** 26/04/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001415827
<b>Claimant Vehicle No :</b>	SBH8888L	<b>Insured Vehicle No :</b>	SLP7151A
Date of Loss:	25/11/2022	Nature of Claim:	TP
		Claim No:	292314

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SBH8888L</b>		
Make & Model:	BMW 528I, 2.0 D/AB 2WD 4DR GAS/D NAV (A)	Engine No:	A2510587N20B20A
Reg. Date:	30/09/2013 (Man. Year: 2013)	Chassis No:	WBASZ62020DZ35833
Colour:	Metallic Dark Grey	Odometer:	132368 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	245/45 R19	Rear Tyre Size:	275/40 R19
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,997.30	4,414.68	3,582.62	44.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	1,630.00	1,920.00	54.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,547.30</b>	<b>6,044.68</b>	<b>5,502.62</b>	<b>47.65</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,800.00</b>		
<b>(S\$)</b>	11,547.30	4,800.00	6,747.30	58.43
<b>+ GST 8.00/8.00% (S\$)</b>	923.78	384.00	539.78	58.43
<b>Nett Amount (S\$)</b>	<b>12,471.08</b>	<b>5,184.00</b>	<b>7,287.08</b>	<b>58.43</b>

**INSPECTION**

Date of Assignment:	30/11/2022	
Date Inspected:	05/12/2022 Inspected At:	Tropical Success Auto Care (HQ) BLK 5032 Ang Mo Kio Avenue 3, #01-303 Industrial Park 2 Singapore 569535
Estimated Period of Repair:	6.0 days	

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2023)
<b>Parts:</b>	143	BMW 528I 2.0 D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SBH8888L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Bent	1,673.00 FL	*1,673.00 FL
2	1		*REAR RH DOOR OUTER HANDLE	Serviceable	940.00 FL	*- FL
3	1		*REAR RH DOOR GLASS OUTER SLIDING MOULDING	Serviceable	60.00 FL	*- FL
4	1		*REAR RH DOOR GLASS INNER SLIDING MOULDING	Serviceable	130.00 FL	*- FL
5	1		*REAR RH DOOR GLASS CHANNEL	Cut	41.00 FL	*41.00 FL
6	1		*REAR RH DOOR WEATHER STRIP (STANDING)	Distorted	81.00 FL	*81.00 FL
7	1		*REAR RH DOOR WEATHER STRIP (SMALL)	Distorted	139.00 FL	*139.00 FL
8	1		*REAR RH DOOR WEATHER STRIP (BIG)	Cut	576.00 FL	*361.20 FL
9	1		*REAR RH DOOR INNER LOCK	Repair	1,349.00 FL	*- FL
10	2		*REAR RH DOOR HINGE	Repair	398.00 FL	*- FL
11	1		*RH DOOR SIDE SKIRT	Bent	756.00 FL	*756.00 FL
12	1		*RH DOOR SIDE SKIRT REAR BRACKET	Distorted	121.00 FL	*121.00 FL
13	1		*REAR RH FENDER	Bent	1,592.00 FL	*1,592.00 FL
14	1		*REAR RH FENDER COWLING	Cracked	141.00 FL	*141.00 FL
15	1		*REAR RH TYRE, PIRELLI P ZERO, 275 / 40 R19 RUN FLAT TYRE	Serviceable	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>8,797.00</b>	<b>4,905.20</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	799.70	490.52
<b>Total Parts (\$)</b>	<b>7,997.30</b>	<b>4,414.68</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	HEAT / WELD / CUT / RENEW REAR RH FENDER, HEAT / WELD / PANEL BEATING / PULL / STRAIGHTEN / ALIGN REAR CHASSIS FRAME BY CHASSIS ALIGNMENT JACK }	New	2,000.00	800.00
2	REMOVE AND TRANSFER REAR RH DOOR NECESSARY ATTACHMENT SPART PART ITEMS }	New	0.00	0.00
3	REMOVE AND TRANSFER REAR RH FENDER NECESSARY ATTACHMENT SPART PART ITEMS }	New	0.00	0.00
4	REMOVE AND REFIT REAR RH DOOR, REAR RH DOOR OUTER HANDLE, REAR RH DOOR GLASS OUTER SLIDING MOULDING, REAR RH DOOR GLASS INNER SLIDING MOULDING, REAR RH DOOR GLASS CHANNEL, REAR RH DOOR WEATHER STRIP (STANDING), REAR RH DOOR WEATHER STRIP (SMALL), REAR RH DOOR WEATHER STRIP (BIG), REAR RH DOOR INNER LOCK, REAR RH DOOR HINGE, REAR RH DOOR SIDE SKIRT, REAR RH DOOR SIDE SKIRT REAR BRACKET }	New	0.00	0.00
5	BALANCING REAR RH WHEEL }	New	50.00	0.00
6	REMOVE AND REFIT REAR RH TYRE }	New	0.00	0.00
7	CONDUCT WHEEL ALIGNMENT TEST	New	120.00	60.00
8	DIANOSTIC AND RESET REAR RH DOOR ELECTRIC COMPONENTS BY HHT	New	100.00	60.00
9	TO CHECK AND REFIT REAR TAIL LAMP WIRING HARNESS	New	80.00	20.00
10	UNDER COATING ON REAR DAMAGED PORTION	New	200.00	30.00
11	PUTTY / PRIMER APPLICATION, SPRAY PAINTING REAR RH DOOR, REAR RH DOOR OUTER HANDLE, REAR RH DOOR HINGES, RH DOOR SIDE SKIRT, REAR RH FENDER	New	1,000.00	660.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,550.00</b>	<b>1,630.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >