

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 69535
TEL: 6481 7771 / 6481 1403 FAX: 6484 4978
E-mail: sac303@singnet.com.sg

M / s : **MSIG Insurance (Singapore) Pte. Ltd**
4, Shenton Way, #21-01, SGX Centre 2,
Singapore 068807

Attn : Motor Claims Department
Tel : 68272888
Fax : 68277800

Estimate bill : TT 43 / 22 / TP / WT
Registration No : SBH8888L
Make / model : BMW 528i GT

Mileage : Date : 03 / 12 / 2022
**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SLP7151A AND SBH8888L ALONG
BLK 16 KALLANG PLACE OPEN CARPARK ON 25 NOVEMBER 2022 AT ABOUT 0930HRS.**

Ipc	Rear RH door	\$	1,673.00
Ipc	Rear RH door outer handle	\$	940.00
Ipc	Rear RH door glass outer sliding moulding	\$	60.00
Ipc	Rear RH door glass inner sliding moulding	\$	130.00
Ipc	Rear RH door glass channel	\$	41.00
Ipc	Rear RH door weather strip (Standing)	\$	81.00
Ipc	Rear RH door weather strip (Small)	\$	139.00
Ipc	Rear RH door weather strip (Big)	\$	576.00
Ipc	Rear RH door inner lock	\$	1,349.00
2pcs	Rear RH door hinge	\$	398.00
Ipc	RH door side skirt	\$	756.00
Ipc	RH door side skirt rear bracket	\$	121.00
Ipc	Rear RH fender	\$	1,592.00
Ipc	Rear RH fender cowlings	\$	141.00
	Sub total :	\$	7,997.00
	Less 10% discount :	\$	799.70
	A total :	\$	7,197.30

Special net items :

Ipc Rear RH tyre, Pirelli P Zero, 275 / 40 R19 Run Flat tyre
B total :

\$ 800.00 X
\$ 800.00

Remove and transfer rear RH door necessary attachment spart part items.

Remove and transfer rear RH fender necessary attachment spart part items.

Remove and refit rear RH door, rear RH door outer handle, rear RH door glass outer sliding moulding, rear RH door glass inner sliding moulding, rear RH door glass channel, rear RH door weather strip (Standing), rear RH door weather strip (Small), rear RH door weather strip (Big), rear RH door inner lock, rear RH door hinge, rear RH door side skirt, rear RH door side skirt rear bracket.

Heat / weld / cut / renew rear RH fender, heat / weld / panel beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.

Total amount of Page 3 :

Tropical Tech Automobile Services



(Authorised Signature)
William Tan

*Not Authorised
6/Dec @ 4800h
Penny After Penny
6 days*

\$ 2,000.00

\$ 7,997.30

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535
TEL: 6481 7773 / 6481 1403 FAX: 6484 4978
E-mail: tsac303@singnet.com.sg

M / s : **MSIG Insurance (Singapore) Pte. Ltd**
4, Shenton Way, #21-01, SGX Centre 2,
Singapore 068807

Estimate bill : TT 43 / 22 / TP / WT

Attn : Motor Claims Department

Registration No : SBH8888L

Tel : 68272888
Fax : 68277800

Make / model : BMW 528i GT

Mileage :

Date : 03 / 12 / 2022
**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SLP7151A AND SBH8888L ALONG
BLK 16 KALLANG PLACE OPEN CARPARK ON 25 NOVEMBER 2022 AT ABOUT 0930HRS.**

Remove and refit rear RH tyre.

Balancing rear RH wheel.

Conduct wheel alignment test.

Diagnostic and reset rear RH door electric components by HHT

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear RH door, rear RH door outer handle, rear RH door hinges, RH door side skirt, rear RH fender.

Balance amount brought from Page 1 :

Grand final amount :

\$	50.00	X
\$	120.00	601
\$	100.00	601
\$	80.00	201
\$	200.00	301
\$	1,000.00	6601
\$	7,997.30	
\$	9,547.30	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

(Authorised Signature)
William Tan