

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

29 NOV 2022

ESTIMATE

Estimate No. : b1 64218
 Date Estimated : 29/11/2022
 Prepared By : Jack Ng Guo Ming

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ravishankar Asokkumar
 3 Bishan Street 15
 #04-20

Singapore 573911

- ACCOUNT - 40000

Cash Sales - Service
 Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNG8106Z	WBA32AA0905U97755	05/09/2022	X1 sDrive18i	70

DESCRIPTION	VALUE
To replace rear bumper and make good tail end panel.	1700 850 3,480.00
To respray rear bumper and tail end panel	986 1,791.00
To carry out body cavity preservation. (Per panel).	XAN? 118.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168 177.00
To check electrical wiring	168 177.00
To replace rear exhaust silencer including alignment system and conduct check for leak.	504 531.00
To replace front exhaust silencer including alignment system and conduct check for leak.	X504 531.00
Sundries.	? 150.00
Total Labour 1: 6,865.00	

DESCRIPTION	QTY	PRIC	VALUE
RR SILENCER CLAMPING BUSH <i>? ne /</i>	1	64.35	64.35
TAILPIPE TRIM BRIGHT CHROME <i>? xan</i>	1	125.55	125.55
REAR SILENCER <i>? 34 /</i>	1	1,108.15	1,108.15
RP PETROL PARTICULATE FILTER (RDE) <i>34 /</i>	1	2,235.50	2,235.50
REAR BUMPER TRIM PANEL (X LINE) <i>see -</i>	1	231.70	231.70
REAR LH BUMPER MOUNT <i>? xan</i>	1	166.90	166.90
REAR RH BUMPER MOUNT <i>? xan</i>	1	166.90	166.90
RP BUMPER CARRIER <i>? xan</i>	1	523.75	523.75
MOUNTING SMART OPENER <i>. xan</i>	1	47.00	47.00
REAR BUMPER PANEL PRIMED <i>repair</i>	1	926.75	926.75
REAR BUMPER MIDDLE TRIM PANEL (PDC) <i>de -</i>	1	272.45	272.45

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 64218**
Date Estimated : **29/11/2022**
Prepared By : **Jack Ng Guo Ming**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SNG8106Z	WBA32AA0905U97755	05/09/2022	X1 sDrive18i	70

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER TOWING EYE COVER <i>XAN</i>	1	37.70	37.70
Total Parts :			5,906.70

Claims OD 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 02/12/22 @ 12:00 Excess S\$ _____

Surveyor's Name RASUL Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 3 days + 3 = 6 days

Req before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	6,865.00
Parts	:	5,906.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	894.02

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 64218
Date Estimated : 29/11/2022
Prepared By : Jack Ng Guo Ming

Page No. :

- ESTIMATE REPAIR FOR -

Ravishankar Asokkumar
3 Bishan Street 15
#04-20

Singapore 573911

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SNG8106Z	WBA32AA0905U97755	05/09/2022	X1 sDrive18i	70

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

- | | | | |
|---|----------|------|------------|
| * To replace rear bumper trim panel, rear trim underride protection, rear bumper middle trim panel include making good the rear bumper panel and knocking out dents caused by the accident. To remove and install front suspension to facilitate the replacement of steering box heat resistant plate | 1,700.00 | 0.00 | 1,700.00 ✓ |
| * To replace RP petrol particulate filter include alignment of system and conducting checks for harmful pollutants | 631.00 | 0.00 | 631.00 ✓ |
| * To replace RP catalytic converter near engine include alignment of system and conducting checks for leak | 504.00 | 0.00 | 504.00 ✓ |

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

- | | | | | |
|---|----------|-------|------|----------|
| # GASKET RING ✓ | 31.05 | 1.00 | 0.00 | 31.05 |
| # V BAND CLAMP ✓ | 44.40 | 1.00 | 0.00 | 44.40 |
| # HOLDER EXHAUST SYSTEM ✓ | 30.30 | 1.00 | 0.00 | 30.30 |
| # RP CATALYTIC CONVERTER NEAR ENGINE b1 ✓ | 2,113.30 | 1.00 | 0.00 | 2,113.30 |
| # STEERING BOX HEAT RESISTANT PLATE ✓ | 66.65 | 1.00 | 0.00 | 66.65 |
| # REAR TRIM UNDERRIDE PROTECTION (X L) ✓ | 151.10 | 1.00 | 0.00 | 151.10 |
| # EXPANDING RIVET BLACK ✓ | 1.40 | 15.00 | 0.00 | 21.00 |

SUPPLEMENTARY ITEMS

Total Labour :	2,835.00
Total Parts :	2,457.80
Total Labour & Parts (before GST) :	5,292.80

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

Page 1 of 1

A Sime Darby Motors Company

Finalised by: Cindy/CT DID: 63190175 Fax: 64794601