

Performance Motors

BMW Dealer



Final Report

Estimate No. : **b1 64218**
Date Estimated : **29/11/2022**
Prepared By : **Jack Ng Guo Ming**

Page No. :

- ESTIMATE REPAIR FOR -
Ravishankar Asokkumar
3 Bishan Street 15
#04-20

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Singapore 573911

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SGN8106Z	WBA32AA0905U97755	05/09/2022	X1 sDrive18i	70

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace rear bumper trim panel, rear trim underride protection, rear bumper middle trim panel include making good the rear bumper panel and knocking out dents caused by the accident. To remove and install front suspension to facilitate the replacement of steering box heat resistant plate	1,700.00	0.00	1,700.00
To respray rear bumper	986.00	0.00	986.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function	168.00	0.00	168.00
To check electrical wiring system and lightings at the rear section for proper function	168.00	0.00	168.00
To replace rear exhaust silencer including alignment of system and conducting checks for leak	504.00	0.00	504.00
* To replace RP petrol particulate filter include alignment of system and conducting checks for harmful pollutants	631.00	0.00	631.00
* To replace RP catalytic converter near engine include alignment of system and conducting checks for leak	504.00	0.00	504.00
Sundries	150.00	0.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
RR SILENCER CLAMPING BUSH	64.35	1.00	0.00	64.35
# GASKET RING	31.05	1.00	0.00	31.05
# V BAND CLAMP	44.40	1.00	0.00	44.40
# HOLDER EXHAUST SYSTEM	30.30	1.00	0.00	30.30

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W



Performance Motors

BMW Dealer



Final Report

REAR SILENCER	1,108.15	1.00	0.00	1,108.15
RP PETROL PARTICULATE FILTER (RDE)	2,235.50	1.00	0.00	2,235.50
# RP CATALYTIC CONVERTER NEAR ENGINE	2,113.30	1.00	0.00	2,113.30
# STEERING BOX HEAT RESISTANT PLATE	66.65	1.00	0.00	66.65
REAR BUMPER TRIM PANEL (X LINE)	231.70	1.00	0.00	231.70
# REAR TRIM UNDERRIDE PROTECTION (X L)	151.10	1.00	0.00	151.10
REAR BUMPER MIDDLE TRIM PANEL (PDC)	272.45	1.00	0.00	272.45
# EXPANDING RIVET BLACK	1.40	15.00	0.00	21.00

SUPPLEMENTARY ITEMS

Total Labour :	4,811.00
Total Parts :	6,369.95
Total Labour & Parts (before GST) :	11,180.95
Deduction for Excess :	
Total Repair Costs less Excess:	11,180.95
GST @8%:	894.48
Grand Total :	12,075.43

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

