



LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

Allianz Insurance Singapore Pte. Ltd

Date : 29 Nov 2022

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLQ6866Y
 CHASSIS NO : JM6BN22A8H0161890
 MAKE / MODEL : Mazda 3
 DATE OF ACCIDENT: 22 Nov 2022
 YOUR INSURED VEHICLE NUMBER : SNB441J

	<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear Bumper <i>tan</i>	1PC	\$1,200.00	\$1,200.00
2	Rear Bumper retainer LH <i>m</i>	1PC	\$60.00	\$60.00
3	Rear Bumper reflector LH <i>ca</i>	1PC	\$180.00	\$180.00
4	Rear Bumper reinforcement <i>bt</i>	1PC	\$580.00	\$580.00
5	Rear bumper lower cover <i>ca</i>	1PC	\$300.00	\$300.00
6	Rear bumper tow cover LH <i>m</i>	1PC	\$30.00	\$30.00
7	Rear boot <i>repair</i>	2PC	\$1,000.00	\$1,000.00 <i>XR</i>
8	Rear boot weatherstrip <i>tan</i>	1PC	\$205.00	\$205.00 <i>X</i>
9	Rear boot SKYACTIV emblem <i>m</i>	1PC	\$50.00	\$50.00
10	Rear boot Mazda logo <i>m</i>	1PC	\$60.00	\$60.00
11	Rear boot Mazda 3 emblem <i>m</i>	1PC	\$45.00	\$45.00
12	Rear taillamp LH <i>ca</i>	1PC	\$580.00	\$580.00
13	Rear taillamp reflector LH <i>tan</i>	1PC	\$320.00	\$320.00 <i>X</i>
14	Rear LH fender <i>bm</i>	1PC	\$330.00	\$330.00
15	Rear LH fender liner <i>? tan</i>	1PC	\$93.00	\$93.00 <i>X</i>
16				

3415
20%
2732

LIST TOTAL S\$: \$5,033.00
 20.00% DISCOUNT S\$: \$1,006.60
 \$4,026.40

	<u>SPECIAL NETT</u>		
1	Rear bumper clips <i>m</i>	1 set	\$100.00 <i>30</i>
2	Fender liner clips <i>m</i>	1 set	\$100.00 <i>30</i>
3	Windscreen sealant <i>m</i>	1 set	\$200.00 <i>40</i>
4	Body sealant <i>m</i>	1 set	\$300.00 <i>60</i>
5	Reverse sensor <i>tan</i>	1 set	\$280.00 <i>tan</i>
Special Nett Total S\$:			\$980.00

160

LABOUR CHARGES

- | | | |
|---|---|-----------------------------|
| 1 | To labour to remove all damage parts out to facilitate repairs and replacement of damage parts | \$1,500.00 800 |
| 2 | To respray all damage and new parts | \$1,400.00 800 |
| 3 | To apply rustproofing on all damaged parts | \$300.00 40 |
| 4 | To check wiring system | \$200.00 30 1750 |
| 5 | Transfer rear boot lock mechanism and remove rear seat and all garnish out to facilitate repairs | \$200.00 X nn |
| 6 | To apply rustproofing on all damaged parts | \$200.00 X nn |
| 7 | To conduct a standard of operating procedures post repairs scan test as a requirements upon completion of collision repairs | \$200.00 80 |

LABOUR TOTAL S\$:	\$4,000.00
TOTAL S\$:	\$9,006.40
7% GST	\$630.45
GRAND TOTAL S\$:	\$9,636.85

2732
160
1750
4642
20%
3713.60
45- \$3,700/7day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Revised
Hf 900100 68
7 days
45
30/11/22 @ 1700
Reg after repair