

JA AUTOCARE PTE LTD

Blk 24, Sin Ming Road

#03-25

Singapore 570024

Tel : 94513429

Liberty Insurance Singapore Pte Ltd

51 Club Street

#03-00 Liberty House

Singapore 069428

ESTIMATE

Date: 25.11.2022

vehicle number: GBK 3433H

Model Nissan van

Chassis/Eng# :

Accident Date : 25.11.2022

Parts Nett items

- 01) Front bumper
- 02) Front bumper bracket lh
- 03) Front bumper retainer lh
- 04) Front bumper clips
- 05) Front bumper inner sponge
- 06) Front bumper reinforcement
- 07) Front bumppt tow cover
- 08) Front bumper lamp lh
- 09) Head lamp lh
- 10) Head lamp clips
- 11) Head Lamp lower panel lh
- 12) Front fender lh
- 13) Front fender inner shield lh
- 14) Front fender inner shield clips

\$ <i>FM</i>	750.00	✓
\$ <i>h</i>	50.00	X
\$ <i>DIT</i>	65.00	✓
\$ <i>h</i>	60.00	✓
\$ <i>h</i>	120.00	X
\$ <i>h</i>	480.00	X
\$ <i>h</i>	65.00	X
<i>NIP</i> \$	250.00	X
\$ <i>h</i>	650.00	✓
\$ <i>h</i>	60.00	✓
<i>ms</i> \$ <i>FM</i>	250.00	✓
\$ <i>h</i>	750.00	✓
\$ <i>CM</i>	250.00	✓
\$ <i>h</i>	60.00	✓
\$	3,860.00	
\$	(386.00)	
\$	3,474.00	

Less 10%

S/Nett

- 15) Front tyre rim lh

\$ <i>h</i>	350.00	X
\$	350.00	

Labour charges

- 16) To checking wiring
- 17) to apply anti rust chemical
- 18) To knock out denst on affected areas and renew parts
- 19) To putty & respray painting

\$	200.00	201
\$	100.00	301
\$	1,000.00	4501
\$	1,400.00	3601
\$	2,700.00	

\$ 6,524.00

for JA AutoCare Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: