TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510

Fax: 67410510 Email: sales@n51.com.sq

Our Ref:

ST 8485 Y

Your ref:

YN 5936 Y

29 November 2022

ALLIANZ INSURANCE SINGAPORE PTE LTD

79 ROBINSON ROAD #09-01 SINGAPORE 068897

Attn: Motor Claims Department

Dear Sir/Madam.

NAME OF CLAIMANT: TAN BOON CHIN

VEHICLE NUMBER: ST 8485 Y

YOUR INSURED VEHICLE NUMBER: YN 5936 Y

ACCIDENT ON 21 NOV 2022 AT ABOUT 13:40 HOURS

ALONG ALEXANDRA ROAD

We refer to your email / fax dated 29 Nov 2022 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-17

Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you! Appointed surveyor:

(Name & Signature):

Date & Time of Inspection:

Twincar Automotive Pte Ltd