

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN BOON CHIN
NO 2A JLN DAMAI 3/1 TMN DAMAI 86200
SIMPANG RENGAM JOHOR
SINGAPORE 86200

Contact : 0127231944, 81811944

TAX INVOICE

Repair Code : CLM15747 TP Allianz

Date in : 29/11/2022 Xiao Chen

Vehicle Num. : ST8485Y

Model : SUBARU FORESTER 2.0I-P

Chassis/Eng# : PLPSJ5KC5HA834387/Y419858

(4/5 = 9950.00)

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIR CLEANER BOX <i>Cashed</i>	1	248.00	✓ 248.00
AIR CLEANER BOX DUCT GARNISH <i>new</i>	1	43.20	✗ 43.20
FRONT BONNET <i>Distorted</i>	1	883.00	✓ 883.00
FRONT BONNET HINGES L/R <i>Best</i>	2	46.00	✓ 92.00
FRONT BONNET INSULATOR MAT <i>new</i>	1	80.00	✗ 80.00
FRONT BONNET INSULATOR MAT CLIPS <i>new</i>	11	2.20	✗ 24.20
FRONT BUMPER <i>torn</i>	1	695.00	✓ 695.00
FRONT BUMPER RH FOG LAMP	1	253.00	✗ 253.00
FRONT BUMPER RH FOG LAMP COVER	1	45.00	✗ 45.00
FRONT BUMPER RH SIDE LAMP	1	105.00	✗ 105.00
FRONT BUMPER RH SIDE LAMP GRILLE COVER <i>new</i>	1	16.00	✗ 16.00
FRONT BUMPER RH WASHER COVER	1	48.00	✗ 48.00
FRONT BUMPER RH WASHER PUMP	1	85.00	✗ 85.00
FRONT BUMPER SIDE RETAINER L/R <i>Right Dmgd</i>	1	25.00 ✓	25 50.00
FRONT RH DOOR <i>Distorted</i>	1	825.00	✓ 825.00
FRONT RH DOOR CHECKER <i>Dmgd</i>	1	65.00	✓ 65.00
FRONT RH DOOR FRAME STICKER (NO:1) <i>new</i>	1	20.00	✓ 20.00
FRONT RH DOOR FRAME STICKER (NO:2)	1	32.00	✓ 32.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TAN BOON CHIN
 NO 2A JLN DAMAI 3/1 TMN DAMAI 86200
 SIMPANG RENGGAM JOHOR
 SINGAPORE 86200

Contact : 0127231944, 81811944

TAX INVOICE

Repair Code : CLM15747

Date in : 29/11/2022

Vehicle Num. : ST8485Y

Model : SUBARU FORESTER 2.0I-P

Chassis/Eng# : PLPSJ5KC5HA834387/Y419858

FRONT RH DOOR FRAME STICKER (NO:3) <i>Nu</i>	1	35.00	✓	35.00
FRONT RH DOOR GLASS <i>ut</i>	1	505.00	✓	505.00
FRONT RH DOOR GLASS CHANNEL SEAL <i>Ne m</i>	1	90.00	✗	90.00 ✗
FRONT RH DOOR GLASS CHANNEL SEAL BRACKET <i>Bent</i>	1	98.00	✓	98.00
FRONT RH DOOR GLASS REGULATOR <i>Damaged</i>	1	300.20	✓	300.20
FRONT RH DOOR HINGES (TOP & LOWER) <i>Bent</i>	2	52.00	✓	104.00
FRONT RH DOOR INNER PLASTIC SEAL COVER <i>Ne m</i>	1	32.00	✗	32.00 ✗
FRONT RH DOOR INNER TRIM BOARD <i>cracked</i>	1	605.00	✓	605.00
FRONT RH DOOR LOWER PROTECTOR <i>cracked</i>	1	220.00	✓	220.00
FRONT RH DOOR MECHANISM LOCK <i>Damaged</i>	1	279.00	✓	279.00
FRONT RH DOOR OUTER MOULDING <i>Distorted</i>	1	122.00	✓	122.00
FRONT RH DOOR PILLAR <i>Repair</i>	1	389.00	✗	389.00 ✗
FRONT RH DOOR QUARTER GLASS <i>ut</i>	1	148.00	✓	148.00
FRONT RH DOOR QUARTER GLASS SEAL <i>ne</i>	1	82.00	✓	82.00
FRONT RH DOOR SIDE MIRROR <i>Distorted</i>	1	558.00	✓	558.00
FRONT RH DOOR SIDE MIRROR COVER <i>Missing</i>	1	155.00	✓	155.00
FRONT RH DOOR SIDE MIRROR HOUSING COVER (OUTER) <i>Distorted</i>	1	72.00	✓	72.00
FRONT RH DOOR SIDE MIRROR LAMP <i>Missing</i>	1	115.00	✓	115.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN BOON CHIN
NO 2A JLN DAMAI 3/1 TMN DAMAI 86200
SIMPANG RENGGAM JOHOR
SINGAPORE 86200

Contact : 0127231944, 81811944

TAX INVOICE

Repair Code : CLM15747

Date in : 29/11/2022

Vehicle Num. : ST8485Y

Model : SUBARU FORESTER 2.0I-P

Chassis/Eng# : PLPSJ5KC5HA834387/Y419858

FRONT RH DOOR SPEAKER	<i>crushed</i>	1	171.00	/	171.00
FRONT RH DOOR WEATHER STRIP SEAL	<i>cut</i>	1	166.00	/	166.00
FRONT RH DOOR WIRE HARNESS	<i>not new</i>	1	181.00	X	181.00 K
FRONT RH FENDER	<i>Dented</i>	1	298.00	/	298.00
FRONT RH FENDER INNER PANEL	<i>Buckled</i>	1	455.00	/	455.00
FRONT RH FENDER INNER PANEL INNER INSULATOR COVER	<i>crumpled</i>	1	80.00	/	80.00
FRONT RH FENDER INNER SHIELD	<i>torn</i>	1	120.00	/	120.00
FRONT RH FENDER LOWER PROTECTOR GARNISH	<i>not new</i>	1	22.00	X	22.00 K
FRONT RH FENDER QUARTER GARNISH	<i>Missing</i>	1	30.00	/	30.00
FRONT RH HEADLAMP	<i>crushed</i>	1	3400.20	<i>2750</i> 3400.20	
FRONT RH HEADLAMP LOWER BRACKET	<i>crushed</i>	1	50.00	/	50.00
FRONT RH HEADLAMP LOWER PANEL	<i>Dented</i>	1	72.00	/	72.00
FRONT RH HEADLAMP TOP PANEL	<i>Buckled</i>	1	85.00	/	85.00
REAR RH DOOR FRAME STICKER (NO:1)	<i>not new</i>	1	30.00	X	30.00 K
REAR RH DOOR LOWER PROTECTOR	<i>not new</i>	1	145.00	X	145.00
REAR RH DOOR OUTER MOULDING	<i>cut</i>	1	112.00	/	112.00

*** This is a computer-generated document which requires no signature.***

page 3

11467.40
- 20) 2293.48
9173.92

10672.20

8537.76

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

TAN BOON CHIN
 NO 2A JLN DAMAI 3/1 TMN DAMAI 86200
 SIMPANG RENGAM JOHOR
 SINGAPORE 86200

Contact : 0127231944, 81811944

TAX INVOICE

Repair Code : CLM15747

Date in : 29/11/2022

Vehicle Num. : ST8485Y

Model : SUBARU FORESTER 2.0I-P

Chassis/Eng# : PLPSJ5KC5HA834387/Y419858

		Subtotal before discount	12,935.80
Percentage discount	20%		2,587.16
		Sub-total 1	10,348.64
FRONT BUMPER CLIPS - SET <i>nu</i>	1	50.00	50.00 30
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET <i>nu</i>	1	50.00	50.00 30
FRONT RH DOOR LOWER PROTECTOR CLIPS - SET <i>nu</i>	1	30.00	30.00 20
FRONT RH DOOR SIDE MIRROR GLASS <i>cancel</i>	1	480.00	480.00 200
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>nu</i>	1	50.00	50.00 30
		Subtotal before discount	550 660.00
Percentage discount	0%		0.00
		Sub-total 2	660.00
		Parts-total	11,008.64

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To reset system after repair works

To remove, reinstall windscreen. (to FR)

To remove, reinstall front suspension undercarriage parts. (to FR)

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

30 80.00
~~x~~ 250.00
~~x~~ 150.00
~~x~~ 180.00
~~x~~ 100.00
~~60~~ 120.00
~~/~~ 80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TAN BOON CHIN
NO 2A JLN DAMAI 3/1 TMN DAMAI 86200
SIMPANG RENGAM JOHOR
SINGAPORE 86200

Contact : 0127231944, 81811944

TAX INVOICE

Repair Code : CLM15747

Date in : 29/11/2022

Vehicle Num. : ST8485Y

Model : SUBARU FORESTER 2.0I-P

Chassis/Eng# : PLPSJ5KC5HA834387/Y419858

To remove, reinstall dashboard fascia, meter reading and etc. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

280.00	x
1,800.00	1200
2,000.00	1200
120.00	60
5,160.00	2730
16,168.64	

*** This is a computer-generated document which requires no signature.***

page 5

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

12453.92
1/5-20) 2490.78
9963.13

Adrian L
1/5 30/11/22
07 Days

total: 11577.26
4/5 9.2K
9.2K
0804p