

Veron Chen (LKKAUTO)

From: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>
Sent: Monday, 12 December 2022 3:02 PM
To: Veron Chen (LKKAUTO); Rasul (LKKAUTO)
Subject: RE: SKQ 7540S-DOA: 27/11/2022 (AIG REF: 8473155387SG)

Hi Veron,

It is approved.

Best Regards,
Kok Chong

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Sent: Monday, December 12, 2022 2:56 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Lim, Kok-Chong <Kok-Chong.Lim@aig.com>
Subject: [EXTERNAL] SKQ 7540S-DOA: 27/11/2022 (AIG REF: 8473155387SG)

This message is from an external sender; be cautious with links and attachments.

Dear Kok Chong,

We have uploaded photos in merimen

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 9 December 2022 4:43 PM
To: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>
Cc: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: RE: SKQ 7540S-DOA: 27/11/2022 (AIG REF: 8473155387SG)

Dear Kok Chong,

Kindly refer attach photos.

Repair kit is necessary to be replace. Dismantling undercarriage is necessary in order to carry out by means of alignment and functionality.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>

Sent: Friday, 9 December 2022 10:01 AM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: RE: SKQ 7540S-DOA: 27/11/2022 (AIG REF: 8473155387SG)

Hi Veron,

Not approve

I am still waiting for Rasul to get back to me on the steering rack damage since yesterday we spoke.

Best Regards,

Kok Chong

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Sent: Thursday, December 8, 2022 11:40 AM

To: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>

Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>

Subject: [EXTERNAL] SKQ 7540S-DOA: 27/11/2022 (AIG REF: 8473155387SG)

This message is from an external sender; be cautious with links and attachments.

Dear Kok Chong,

Refer to the above mentioned.

Supplementary item no. 4 not approved

According to surveyor, Is necessary, this is the clip and clamp for the steering track rod bush.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must

not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.