

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1063/2022/TF
DATE : 29-Nov-22
WIP : 52439

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/11/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS JULIE CHEW LI CHIN
ADDRESS : 28 JALAN DATOH
#31-08
SINGAPORE 329426
TELEPHONE : HP +65 96361197
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100397324-07
VEHICLE NO : **SKQ 7540 S**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 24/12/2014
ENGINE NO : CZD 898315
CHASSIS NO : WAUZZZF3XL1118846
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 27-Nov-22
PLACE OF ACCIDENT : SIGLAP RD JUST AFTER ECP TURNOUT

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKQ 7540 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	? 250?
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$ 2,400.00	1500
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER. <i>RHS front door.</i>	\$ 2,500.00	1650
5	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUFBRAKE.	\$ 3,200.00	?
SUB-TOTAL LABOUR CHARGES		: \$ 8,860.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKQ 7540 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUFBRAME.	S/N \$ 520.00	/
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 384.00	/
TOTAL LABOUR CHARGES		: \$ 9,764.00	




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKO 7540 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>sur</i>	1	\$ 1,205.00	
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$ 114.00	
3	FRONT BUMPER SPOILER <i>sur</i>	1	\$ 426.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$ 196.00	
5	FRONT BUMPER AIR GRILLE - RH <i>sur</i>	1	\$ 132.00	
6	FRONT BUMPER AIR GRILLE TRIM - RH <i>?</i>	1	\$ 27.00	
7	FRONT BUMPER FORM FILLER PIECE <i>X</i>	1	\$ 114.00	
8	FRONT BUMPER REINFORCEMENT <i>X</i>	1	\$ 974.00	
9	FRONT BUMPER REINFORCEMENT COVER <i>X</i>	1	\$ 73.00	
10	FRONT BUMPER STRIKER PLATE <i>?</i>	1	\$ 146.00	
11	FRONT BUMPER TOP COVER <i>X</i>	1	\$ 137.00	
12	CAUTION STICKER <i>X</i>	1	\$ 16.00	
13	FRONT BUMPER SUPPORT - LH / RH <i>X</i>	2	\$ 56.00	
14	FRONT FENDER BRACE RH - UPPER / LOWER <i>?</i>	2	\$ 134.00	
15	FRONT FENDER - RH <i>bt</i>	1	\$ 1,014.00	
16	FRONT FENDER ATTACHMENT PARTS <i>X</i>	1	\$ 73.00	
17	FRONT FENDER BRACKET <i>bt</i>	1	\$ 92.00	
18	FRONT FENDER RIVET <i>✓</i>	12	\$ 36.00	
19	FRONT FENDER BRACE RH - FRONT <i>?</i>	1	\$ 116.00	
20	FRONT FENDER CLOSING ELEMENT - RH <i>?</i>	1	\$ 37.00	
SUB TOTAL SPARE PARTS		:	\$ 5,118.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 7540 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER - RH ?	1	\$ 260.00	
22	FRONT WHEEL SPOILER - RH can	1	\$ 152.00	
23	HEADLIGHT MOUNTING - RH ?	1	\$ 132.00	
24	HEADLIGHT RETAINING PLATE - RH ?	1	\$ 97.00	
25	HEADLIGHT - RH ?	1	\$ 2,182.00	
26	HEADLIGHT LIFT CYLINDER - RH X	1	\$ 231.00	
27	HEADLIGHT LIFT CYLINDER HOSE X	1	\$ 204.00	
28	FRONT FOG LAMP - RH X	1	\$ 304.00	
29	FRONT WHEEL ARCH TRIM - LH / RH ne	2	\$ 544.00	
30	GROMMET ?	18	\$ 53.00	
31	FRONT RIM - RH so	1	\$ 1,414.00	
32	RUBBER VALVE ne	1	\$ 4.00	
33	FRONT ASSEMBLY CARRIER ?	1	\$ 1,567.00	
34	FRONT WISHBONE - RH ?	1	\$ 520.00	
35	FRONT WHEEL BEARING HOUSING - RH ?	1	\$ 628.00	
36	FRONT GUIDE JOINT - RH ?	1	\$ 139.00	
37	FRONT STABILIZER ?	1	\$ 467.00	
38	FRONT COUPLING ROD ?	1	\$ 105.00	
39	FRONT WHEEL BEARING - RH ?	1	\$ 486.00	
40	FRONT ABSORBER - RH ?	1	\$ 364.00	
SUB TOTAL SPARE PARTS			\$ 9,853.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-22/07/22



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKQ 7540 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT DRIVER SHAFT ?	1	\$ 1,521.00	
42	FRONT STEERING RACK ?	1	\$ 5,552.00	
43	FRONT TRACK ROD - RH ?	1	\$ 99.00	
44	FRONT TIE ROD END - RH ?	1	\$ 126.00	
45	FRONT TYRE - RH X	1	TBC	
46	SUNDRIES X		\$ 1,000.00	
47	SUNDRIES ?		\$ 300.00	
TOTAL SPARE PARTS		:	\$ 23,569.00	
TOTAL LABOUR CHARGES		:	\$ 9,764.00	
GRAND TOTAL		:	\$ 33,333.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-22/07/22

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: Rasm - Hp 9001 0068
: 29/11/22 @ 1650
: 5 deep
: EXCESS: TDA
: Revert
: Res before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT