

Not Authorized
Phoney B4pam



3 days
L1 Bny @ 6250/p

ESTIMATE TO REPAIR

VEHICLE NO. : SLB 4822 R
MAKE : JAGUAR
MODEL : XE 2.0 14P TSS
YEAR : 2015
CHASSIS NO : SAJAB4AG4GA914405

SURVEYOR NAME :
DATE OF SURVEY : 29 Nov 2022
TIME OF SURVEY : 10:41:24

DATE : 29-Nov-22
DATE OF ACCIDENT : 28-Nov-22
THIRD PARTY REF : GBD 8605 H
THIRD PARTY REF : EQ INSURANCE CO LTD

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1pc	front bumper 2120			my CM	\$ 5,300.00
1pc	front bumper reinforcement 1012			\$ R	\$ 1,200.00
1pc	front no plate garnish			\$ S	\$ 105.00
1pc	front grille			\$ CM	\$ 535.00
1pc	n/s head lamp 3949			\$ CM	\$ 4,990.00
1pc	front support panel			\$ R	\$ 1,850.00
	Less 10%				\$ 13,980.00
					\$ 1,398.00
					\$ 12,582.00
1pc	front no plate	S.Nett		\$ Net	\$ 40.00
	To putty & spray paint			\$	\$ 1,200.00
	To check front wiring & focus head lights			\$	\$ 30.00
	Labour charges			\$	\$ 800.00
TG/VL	TOTAL				\$ 14,652.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: