
Enquire Vehicle's Insurance Particulars

Enquire Vehicle's Insurance Particulars (As At 27 Sep 2022 / 16:15:00)





You have successfully logged out.

Your last login date and time was 29 Sep 2022, 10:35:04. To return to ONE.MOTORING, please click here

For security reasons, please CLEAR YOUR CACHE after each session.

Session Transaction History

S/No.	Asset Type:	Asset ID‡	Transaction Type:	Transaction Amount(\$\$)
1	Vehicle	SNG7454A	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

Providence Automobile Pte Ltd

No 11, Kaki Bukit Road 1, #03-08 Eunos Technolink Singapore 415939 Tel: 6743 3559 Fax: 6743 8051

TAX INVOICE

Bill To: LIN HUA

Date

: 17.10.2022

Invoice No

: PVA-AC-10-113-22

Make/Model

: HONDA VEZEL 1.5X

Vehicle No

: SLQ 3022 K

Payment Terms: CASH / NETS / CREDIT CARD

GST Reg No

: 201128758G

S/N

Singapore

Next Service

DESCRIPTIONS

KM

QTY

AMOUNT

BEING LUMP-SUM REPAIR FOR VEHICLE NO. SLQ 3022 K

8,400.00

Total Amount 8,400.00 Add 7% GST 588.00 **Amount Due** 8,988.00

(SGD: EIGHT THOUSAND NINE HUNDRED AND EIGHTY-EIGHT ONLY)

ROVIDENCE AUTOMOBILE PTE LTD

Authorised signatory

Tommie Lim Appraisal

Block 126 Bishan Street 12 #08-147 Singapore 570126 Handphone No.: +65 97475163 Email: tommie126@yahoo.com.sg ROC: 53448442E

INVOICE

To : Providence Automobile Pte Ltd

Block 7 Kaki Bukit Road 1

#02-08 Eunos Technolink

Singapore 415939

Date

: 07 Oct 2022

Terms

: 30 Days

Invoice No. : TLA/2022/09/006

Due Date

: 07 Nov 2022

Vehicle No.: SLQ3022K

DESCRIPTION	AMOUNT
Service rendered for appraisal / inspection report :	
Professional inspection fees	\$ 813.00
Photographs 93 pcs	
Transport fees	
Re-inspection fees (work in progress, post repair inspection)	
Cheque payment is preferred and should be made to:	
Tommie Lim Appraisal	
Or UEN (Paynow): 53448442E	
GRAND TOTAL	\$ 813.00

TOMMIE LIM\APPRAISAL

Tommie Lim Appraisal

Block 126 Bishan Street 12 #08-147 Singapore 570126 Handphone No.: +65 97475163 Email: tommie126@yahoo.com.sg ROC: 53448442E

VEHICLE INSPECTION REPORT

To:

LIN HUA

c/o :

Providence Automobile Pte Ltd

Block 7 Kaki Bukit Road 1 #02-08 Eunos Technolink

Singapore 415939

REFERENCE

Ref. no.	:	TLA/2022/09/006	3rd party Veh.	:	SNG7454A
Accident on	:	27 Sep 2022	Claim tyre	:	Third Party
Assign on	:	28 Sep 2022	Claim no.	:	To be advice
Inspection on	:	28 Sep 2022	Policy no.	:	To be advice
	:	Providence Automobile Pte Ltd	Finalize on	:	06 Oct 2022
Inspection at	:	Block 7 Kaki Bukit Road 1	Final report on	:	07 Oct 2022
		#02 00 E T11' 1			

#02-08 Eunos Technolink Singapore 415939

PARTICULARS OF DAMAGED VEHICLE

Registration no.	: SLQ3022K	Odometer	: 36181 KM
_			
Make	: HONDA	Chassis no.	: RU11209753
Model	: VEZEL	Transmission	: AUTOMATIC
Regn. date	: 30 Jul 2017	Engine no.	: L15B4409753
Body colour	: RED	Engine cap.	: 1496 CC

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering	:	Affected	Paintwork	:	Good
Footbrake	:	In order	Undercarriage	:	Affected
Handbrake	:	In order	Gen. condition	:	Good

TYRE CONDITION ON VEHICLE

		Make	Size	Tread depth	Type of road wheel
Front N/S	:	Yokohama	215/60R16	70%	Alloy
Front O/S	:	Yokohama	215/60R16	70%	Alloy
Rear N/S	:	Yokohama	215/60R16	80%	Alloy
Rear O/S	:	Yokohama	215/60R16	80%	Alloy

NOTE: The above percentages represent the estimated remaining life of tyre threads.

POINT OF IMPACT



SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT

The impact of the collision has damaged/affected the front bumper assy, front o/s fender assy, front o/s headlamp, front grille assy, front o/s rim, front o/s undercarriage and etc...

Please refer to Annex A (Appraisement Schedule) for a detailed account of the damages and photographs taken.

Note: Reinspection vehicle on 30/09/2022 for repair in progress.

RECOMMENDATION

The estimate cost of repair submitted by Messrs Providence Automobile Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairers have agreed to undertake the repairs to the owner's satisfaction at our revision. We have not authorised the repairs.

Our adjusted cost of repair is SGD 8,400.00 to carry out the repairs. Please refer to Annex A (Appraisement Schedule) for a detailed account of the cost estimates.

REMARKS

We have not authorised the repair. However, for information, under normal circumstances, the repair would takes approximately <u>6 (SIX)</u> working days to complete.

In accordance to your instruction, we have **NOT AUTHORISED** the repair to the damaged vehicle and the survey was conducted strictly on a "WITHOUT PREJUDICE" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Appraisal Report, which includes evidence photographs.

Yours faithfully,

Tommie Lim Apprais

Tommie Lim

Motor Vehicle Appraiser



APPRAISEMENT SCHEDULE

Registration no. : SLQ3022K

Vehicle Model : HONDA

VEZEL

LIST ITEMS	S/N	Qty	Description	Condition	Estimate by	Adjusted
1					Wshop SGD	Amt SGD
2			<u>LIST ITEM S</u>			
1	1	1	Front RH door	Repair	1.289.00	0.00
1 Front RH fender Buckled S58.70 S58.70	2	1	Front RH door weatherstrip	_		
1	3	1				
Second S	4	1	Front RH fender inner shield			
Front RH fender arch protector	5	1 set	Front RH fender inner shield clips	Cracked		
1 Set Front RH fender arch protector clips Cracked 2,145.90 2,155.40 2,256.28 2,	6	1	Front RH fender arch protector			
Front RH headlamp Cracked 2,145.90 2,145.90 2,145.90 1 Front RH headlamp lower bracket Cracked 235.40 235.40 235.40 10 1 Front bumper Deformed / cracked 2,050.10 1,	7	1 set	Front RH fender arch protector clips	Cracked	53.50	
1	8	1		Cracked		
10	9	1	Front RH headlamp lower bracket	Cracked		
1	10	1	Front bumper	Deformed / cracked	1,050.10	
13	11	2	Front bumper side retainer	Deformed / cracked	256.28	
14	12	1 set	Front bumper clips	Cracked	53.50	53.50
15	13	1	Front bumper fog lamp	Serviceable	456.70	0.00
Front bumper lower spoiler Grazed / Deformed 485.60 485.60 17 1 Front bumper lower spoiler rubber Serviceable 202.10 0.00 0.00 18 Iset Front bumper lower spoiler rubber clips Cracked 53.50 53.50 53.50 19 1 Front bumper lower spoiler rubber clips Cracked 53.50 53.50 53.50 19 1 Front bumper lower grille Serviceable 180.10 0.00 0.00 1 Front RH shock absorber Bent 571.30 571.30 571.30 571.30 19 1 Front RH lower arm Bent 488.90 489.90 489.90 489.90	14	1	Front bumper fog lamp garnish	Grazed	176.60	176.60
17	15	1	Front bumper reinforcement	Serviceable	588.25	0.00
18	16	1		Grazed / Deformed	485.60	485.60
1	17	1	Front bumper lower spoiler rubber	Serviceable	202.10	0.00
1 Front RH shock absorber Bent 571.30 571.30 21 1 Front RH lower arm Bent 488.90 488.90 22 1 Front RH knuckle arm Bent 561.60 561.60 23 1 Front RH knuckle arm bearing Jammed 197.60 197.60 24 1 Front stablizer bar Serviceable 195.80 0.00 25 1 Front stablizer bar RH link Bent 195.80 195.80 26 1 Front RH drive shaft Serviceable 588.50 0.00 27 1 Front grille Serviceable 582.30 0.00 28 1 Front grille logo (H) Necessary 89.10 89.10 29 1 Front grille base Cracked 413.60 413.60 30 1 Front grille chrome Serviceable 368.10 0.00 31 1 Front grille top bracket Serviceable 198.10 0.00 32 Iset Front grille clips Cracked 53.50 53.50 33 1 Wiper tank Serviceable 265.80 0.00 34 1 Wiper tank Serviceable 150.80 0.00 35 1 Front RH wind mirror Grazed 994.50 994.50 36 1 Front RH wind mirror Grazed 994.50 994.50 36 1 Front RH wind mirror Repair 125.30 0.00 1 Tront RH wind mirror Repair 125.30 0.00	18	1 set	Front bumper lower spoiler rubber clips	Cracked	53.50	53.50
1 Front RH lower arm Bent 488.90 488.90 22 1 Front RH knuckle arm Bent 561.60 561.60 561.60 23 1 Front RH knuckle arm bearing Jammed 197.60 197.60 197.60 24 1 Front stablizer bar Serviceable 195.80 0.00 25 1 Front stablizer bar RH link Bent 195.80 195.80 26 1 Front RH drive shaft Serviceable 588.50 0.00 27 1 Front grille Serviceable 582.30 0.00 28 1 Front grille logo (H) Necessary 89.10 89.10 29 1 Front grille base Cracked 413.60 413.60 30 1 Front grille chrome Serviceable 368.10 0.00 31 1 Front grille top bracket Serviceable 198.10 0.00 32 1 1 Front grille clips Cracked 53.50 53.50 33 1 Wiper tank Serviceable 265.80 0.00 34 1 Wiper tank Serviceable 150.80 0.00 35 1 Front RH wind mirror Grazed 994.50 994.50 36 1 Front RH wind mirror Grazed 994.50 994.50 36 1 Front RH wind mirror Repair 125.30 0.00 14,982.43 8,988.48 16,000 16,00		1		Serviceable	180.10	0.00
22		1		Bent	571.30	571.30
1 Front RH knuckle arm bearing Jammed 197.60 197.60 24 1 Front stablizer bar Serviceable 195.80 0.0		1		Bent	488.90	488.90
24		1		Bent	561.60	561.60
25		1		Jammed	197.60	197.60
26 1 Front RH drive shaft Serviceable 588.50 0.00 27 1 Front grille Serviceable 582.30 0.00 28 1 Front grille logo (H) Necessary 89.10 89.10 29 1 Front grille base Cracked 413.60 413.60 30 1 Front grille chrome Serviceable 368.10 0.00 31 1 Front grille top bracket Serviceable 198.10 0.00 32 1 set Front grille clips Cracked 53.50 53.50 33 1 Wiper tank Serviceable 265.80 0.00 34 1 Wiper tank motor Serviceable 150.80 0.00 35 1 Front RH wind mirror Grazed 994.50 994.50 36 1 Front RH wind mirror cover Repair 125.30 0.00		1		Serviceable	195.80	0.00
Serviceable		1		Bent	195.80	195.80
28 1 Front grille logo (H) Necessary 89.10 89.10 29 1 Front grille base Cracked 413.60 413.60 30 1 Front grille chrome Serviceable 368.10 0.00 31 1 Front grille top bracket Serviceable 198.10 0.00 32 1 set Front grille clips Cracked 53.50 53.50 33 1 Wiper tank Serviceable 265.80 0.00 34 1 Wiper tank motor Serviceable 150.80 0.00 35 1 Front RH wind mirror Grazed 994.50 994.50 36 1 Front RH wind mirror cover Repair 125.30 0.00		1	Front RH drive shaft	Serviceable	588.50	0.00
29 1 Front grille base Cracked 413.60 413.60 30 1 Front grille chrome Serviceable 368.10 0.00 31 1 Front grille top bracket Serviceable 198.10 0.00 32 1 set Front grille clips Cracked 53.50 53.50 33 1 Wiper tank Serviceable 265.80 0.00 34 1 Wiper tank motor Serviceable 150.80 0.00 35 1 Front RH wind mirror Grazed 994.50 994.50 36 1 Front RH wind mirror cover Repair 125.30 0.00 Less 20% / 20% 2,996.49 1,797.70				Serviceable	582.30	0.00
30		1		Necessary	89.10	89.10
31 1 Front grille top bracket Serviceable 198.10 0.00 32 1 set Front grille clips Cracked 53.50 53.50 33 1 Wiper tank Serviceable 265.80 0.00 34 1 Wiper tank motor Serviceable 150.80 0.00 35 1 Front RH wind mirror Grazed 994.50 994.50 36 1 Front RH wind mirror cover Repair 125.30 0.00 Less 20% / 20% 2,996.49 1,797.70		1		Cracked	413.60	413.60
32 1 set Front grille clips Cracked 53.50 53.50 33 1 Wiper tank Serviceable 265.80 0.00 34 1 Wiper tank motor Serviceable 150.80 0.00 35 1 Front RH wind mirror Grazed 994.50 994.50 36 1 Front RH wind mirror cover Repair 125.30 0.00 Less 20% / 20% 2,996.49 1,797.70					368.10	0.00
33 1 Wiper tank Serviceable 265.80 0.00 34 1 Wiper tank motor Serviceable 150.80 0.00 35 1 Front RH wind mirror Grazed 994.50 994.50 36 1 Front RH wind mirror cover Repair 125.30 0.00 Less 20% / 20% 2,996.49 1,797.70		1		Serviceable	198.10	0.00
34 1 Wiper tank motor Serviceable 150.80 0.00 35 1 Front RH wind mirror Grazed 994.50 994.50 36 1 Front RH wind mirror cover Repair 125.30 0.00 Less 20% / 20% 2,996.49 1,797.70				Cracked	53.50	53.50
35 1 Front RH wind mirror Grazed 994.50 994.50 36 1 Front RH wind mirror cover Repair 125.30 0.00 Less 20% / 20% 2,996.49 1,797.70			•		265.80	0.00
36 1 Front RH wind mirror cover Repair 125.30 0.00 Less 20% / 20% 2,996.49 1,797.70						0.00
Less 20% / 20% 2,996.49 1,797.70						
Less 20% / 20%2,996.49 1,797.70	36	1	Front RH wind mirror cover	Repair	125.30	0.00
Less 20% / 20%2,996.49 1,797.70					14,982.43	8,988.48
				Less 20% / 20%	,	
						7,190.78



APPRAISEMENT SCHEDULE

Registration no. : SLQ3022K

SPECIAL NETT ITEMS

1	,	F1 1	0 1 11	50.00	0.00
1	1	Front number plate	Serviceable	50.00	0.00
2	1	Front number plate holder	Cracked	50.00	30.00
3	1	Front RH rim	Grazed / Cut	600.00	450.00
4	1	Front RH tyre	Serviceable	300.00	0.00
				1,000.00	480.00
		TOTAL		12,985.94	7,670.78

S/N	Qty	Description	Condition / Remarks	Estimate by Wshop SGD	Adjusted Amt SGD
		LABOUR & MISC CHARGES			
1		To remove the affected parts, all relevant attachment, fitting to commence repairs, replace the damages parts, reinstall & realign all necessary parts		1,600.00	1,000.00
2		To disconnect wire harness of electrical component to facilitate repairs, reconnect and check functions.	omponent to facilitate repairs, reconnect and		40.00
3		To apply undercoating on the accident repair and replaced panel for rust protection.		50.00	30.00
4		Dignostic & reset fault code		400.00	200.00
5		To conduct rim balancing		100.00	30.00
6		To remove, renew and refit the front undercarriage to facilitate repair		300.00	200.00
7		To remove, renew and refit tyre		50.00	30.00
8		To remove, renew and refit rack & pinion assy to facilitate repair		400.00	200.00
9		Supply spray paint material and necessary items to respray all accident damage parts and other affected area / panel.		1,600.00	1,000.00
10		To conduct wheel alignment		150.00	100.00
		TOTAL		4,700.00	2,830.00
		Total Parts and Labour Cost of Repair Less 20% (Lumpsum repair adjustment)		17,685.94	10,500.78 2,100.16 8,400.63
		Adjusted Parts and Labour Cost of Repair			8,400.00

OFFICIAL RECEIPT

No.: 11293

Date: 10/10/2022

兹收到 Received from ___

支付大銀 the sum of Dollars ________

系还 in payment of car Renfall from 27/09/2022 to 10/10/2022 (SJY64334)

\$ 1,560.00

Cash / Cheque No.:

S.A Asia International Pte Ltd

LEASING AGREEMENT			VLA No : 11293
DRIVER'SPARTICULARS			
Name as in NRIC : Lin Hu	9		NRIC NO : \$27 166379
Address: : 17 fasir Ris	Grove #04-19		S'pore: : 518143
H/P No: : 9857 8308	Hme No : -		Office No:
Driving Pass Date : 07/04/2	2010 VOCATIONAL LIC:	en menne, generalise men en e	Date of Birth : 61 / 11 / 1967
Control of the Contro			
Make/Model : Toyuta	wish		Vehicle No : Sゴy 6433U
Capacity : 2.0 A	Engine No : 3 Z RA 51	9126	ChassisNo : 5TDQJ20W 80S003243
colour : white	Type : Normal 🔽	OPC 🖂	
PAYMENT / PERIOD			
Agreed leasing period for 13	(Nos of days) fr	om_27/09/	1242 to 10/10/2022
Leasing rate is at S\$ 120	per (day / week /	' month) Deposi	t S\$ received on
(date) total r	ental fee S\$ <u>(560</u>	received o	on(date)
Payment mode via Cheque, Chequ	e No	Bank	/Paynow/Qash)
Driver Signature Date Out 1730 lws Mileage Fuel Level Driver 1770 12022 1508 Fuel Level Driver 1770 12022 1508 Fuel Level Fuel Level		Driver Signature Date In Time In Mileage Fuel Level	10/10/2022 170 UNS 165292 3 quarter
I Lin Hun leasing Terms and Condition stated ov by signing ats the space given below		No. <u>S271663</u> nd shall be respon	37 जhave read and agreed to the sible of the vehicle during the leasing period
Sign for and on behalf of			Driver's signature
S.A. ASIA INTERNATIONAL PTE LTD	A CRAN		Liften
Authorised signatory	•	Name	: Lin Hug
· · · · · · · · · · · · · · · · · · ·		NRIC No	: <u>827166376</u>
Payment method via bank transfer	to		
S.A Asia International Pte Ltd		Remarks	
UOB Ltd (Current) Account			
Account Number 310-305-62			İ
PAYNOW UEN NO 201608987	E		

TERMS AND CONDITION FOR VEHICLES LEASING

We (hereinafter called "the Company" which expression shall where the context so admits include the owner's successor-in title) hereby agrees to lease the vehicle to the name driver/company named herein (therein-after called "Driver"/ "Company") agrees to below subject of the following terms and conditions:-

- The said vehicle may only be driven by the lessee upon approval from the Company. Usage is strictly for own legal purposes 1.
- You must be in possession of a valid driving license and shall at all times drive the said vehicle in a careful and skilful manner, 2. observing the traffic regulations and laws.

3.

- The lessee shall pay to the Company upon execution of this Leasing Contract a deposit ("the Deposit") the amount of which shall be determined by the Leasing Company.
- The Deposit will be refundable in 5 working days upon returning the vehicle as in good conditions.

4. **PAYMENT**

The Price for the Vehicle shall be as stated in this Leasing Contract. The Lessee shall, in addition, pay all GST (if any) payable thereon at the prevailing rate.

The Lessee shall within make the payment on weekly basis. (apply for weekly basis) b.

The Lessee shall within make the payment on monthly basis. (apply for monthly basis) c.

- Failing to pay late charge will be imposed at \$20 per week and interest of 5% per weekly is apply. (apply on d. weekly basis)
- Failing to pay late charge will be imposed at \$80 per month and interest of 5% per month is apply. (apply on e. monthly basis)

5. BREACH

If the Lessee defaults in making any payment due hereunder or if he/she shall fail to observe or comply with any of the terms and conditions of this Leasing Contract herein contained (without prejudice to any other rights and claims the Company may consequentially have against the Lessee) the Company shall be at liberty to do all or any of the following without notice to the Lessee:

Terminate this Leasing Contract; a.

Towing back the Vehicle at Lessee own cost b.

Weekly / Monthly leasing is liable by Lessee in full till end contract. Deposit will be forfeited.

6.

The said vehicle shall be covered under a Comprehensive (COMP) / Third Party (TP) / Third Party Fire & Theft Insurance (TPFT) Policy only. (Singapore usage only)

An additional access for (COMP) of \$3,000 is liable for own damage and \$3,000 for third party claimed and \$214 for windscreen to be bared by the Lessee. As for (TP) Lessee will be liable for own damage claim and windscreen at full cost and \$4,000 for third party claimed. As for (TPFT) Lessee to be bared full cost liable for own damage claim \$3,000 access for third party claimed and full cost for windscreen to be bared by the Lessee.

To sign the overlap leasing agreement and shall immediately examine the state and condition of the vehicle, including the paint and body work of the vehicle, and shall forthwith notify the Company of any damage and / or defects whatsoever to

Access payment has to be made in full immediately upon accident reporting

- If fails to do so, you shall be deemed to have accepted and agreed that the vehicle is in all respects in a good physical 7. condition, roadworthy, in a proper and safe working condition and fully equipped with audio equipment, fitting, accessories,
- In the event of any breach thereof, you (Lessee) shall bare all responsibilities of any parking fines, demerit points and 8. penalties which may be incurred and shall also answer all Police and Traffic Court Summonses, Notices and Inquiries in connection therewith. Particular attention is to be accorded to the following:-

Vehicle must not be overloaded at all times.

To ensure the vehicle is clean and good conditions with sufficient radiator water, black/white smoke and the prescribed of tyre pressure. Tampering with speedometer is strictly prohibited.

Towing of vehicle break down to be bare by the Lessee

d. All tyres of ware and tare and tyres punctured to be bared by Lessee

e. Vehicle maintenance, repair and etc strictly only allow to our authorize workshop.

Shall not drive the said vehicle whilst under the influence of intoxicating liquor or drugs f.

- It is expressly forbidden to allow the said vehicle out to third persons or to let unauthorized persons or learners to use the said vehicle or to permit the said vehicle to be used for illegal purposes (for instance : in connection with theft, drug pedaling or trafficking, smuggling or any other criminal activity) or the purposed of test or racing. Failure to comply may entail serious consequences as you assumes full responsibility and in the event of the said vehicle being seized, confiscated or forfeited as a result thereof, you shall indemnify the Company for all losses incurred including the value of the said vehicle
- You shall report all incidents involving the said vehicle to the Company immediately after the accident. 9.

You shall not admit or compound any claim either partially or in full. 10.

- To secure the names and addresses of all witnesses as well as the registration number of all vehicles involved in the accident. 11.
- All communications or letters received from third parties are to be referred to the Company immediately and not abandon the 12. said vehicle without adequate provisions for safe guarding and securing the same. Failure to comply with, will render you are liable for all cost and third party claims.

Company shall not under any circumstances be liable to make any payment to you in respect of or to indemnify you against 13. any loss, injury or damage sustained by you or by any third party as a result of the use of the said vehicle or as a result of any

defect therein.



MX1 70000231 COV.Type: Comprehensive

CERTIFICATE OF INSURANCE

• MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) • MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 • ROAD TRANSPORT ACT, 1987 (MALAYSIA) • MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

CERTIFICATE No. MA020682

. Index Mark and Registration

Number of Vehicle

SLQ3022K

2. Name of Policyholder

LIN HUA

B. Effective Date of Commencement of

Insurance for the purposes of the Act

03/07/2022

Engine No.: L15B4409753 Chassis No.: RU11209753

Excess (Named Drivers): S\$500.00
Excess (Unnamed Drivers): S\$1000.00

4. Date of Expiry of Insurance

02/07/2023

Persons or Class of Persons entitled to drive

(A) THE POLICYHOLDER

(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION

LIN HUA

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATIONS IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use

USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS OR PROFESSION.

THE POLICY DOES NOT COVER:

(i) USE FOR HIRE OR REWARD.

(ii) USE FOR RACING, PACE MAKING, RELIABILITY TRIAL OR SPEED-TESTING.

(iii) USE FOR THE CARRIAGE OF GOODS (OTHER THAN SAMPLES) IN CONNECTION WITH ANY TRADE OR BUSINESS.

(iv) USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Jection 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Policy Owners' Protection Scheme

This policy is protected under the Policy Owners' Protection Scheme which is administered by the Singapore Deposit Insurance Corporation (SDIC). Coverage for your policy is automatic and no further action is required from you. For more information on the types of benefits that are covered under the scheme as well as the limits of coverage, where applicable, please contact your insurer or visit the General Insurance Association Of Singapore (GIA) / Life Insurance Association Singapore (LIA) / SDIC websites (www.sdic.org.sg / <a href="https://wwww.

I/WE HEREBY CERTIFY that the policy to which this Certificate relates to is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV for the Road Transport Act, 1987 (Malaysia).

For and on behalf of **Etiqa Insurance Pte. Ltd.**Approved Insurer

Authorised Signature

zul@juseq.com.sg

From:

zul@juseq.com.sq

Sent:

Thursday, September 29, 2022 10:54 AM

To:

Motor Claim - III

Cc:

'claims@juseq.com.sg'

Subject:

NOTICE OF ACCIDENT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING

SLQ3022K AND SNG7454A ON 27.09.2022 @ ABOUT 1615 HOURS

Attachments:

REPORT-SLQ3022K.pdf

Dear Sirs

Your Ref: SNG7454A

Our Ref: JEQ/ SLQ3022K /0922 (PM)

NOTICE OF ACCIDENT - PRE-REPAIR INSPECTION - OUR CLIENTS' / CLIENT'S VEHICLE: SLQ3022K

We act for the owner / owners of motor vehicle no. **SLQ3022K**.

We are instructed to claim for damages against you in connection with the above accident and copy of our clients' / client's GIA report is attached herewith for your attention.

Pursuant to the State Courts Practice Directions 2021, Appendix B: Pre-action Protocol for Personal Injury Claims and Non-Injury Motor Accident Claims, paragraph 2, we hereby give you notice to conduct a pre-repair inspection of our clients' / client's motor vehicle no. SLQ3022K.

We would like to inform that our clients / client will be sending their / his / her vehicle no. SLQ3022K to the workshop as stated below: -

Providence Automobile Pte Ltd

No. 11 Kaki Bukit Road 1 #03-08 Eunos Technolink Singapore 415939 Tel: 6743 3559

rAKE NOTICE that you are required to respond to us <u>within 2 working days</u> (excluding Saturday, Sunday and Public Holiday) of receipt of this notice as to whether you wish to carry out or waive a pre-repair inspection. If we do not hear from you in this regard by the stipulated time, we shall construe your silence as waiver of the requirement for a pre-repair inspection and our clients' / client's repairers shall proceed to repair our clients' / client's vehicle no. SLQ3022K.

We look forward to hearing from you by the stipulated time.

With Regards

Zul

On behalf of Mr. Caleb Tan
JusEquity Law Corporation
133 New Bridge Road #10-03
Chinatown Point
Singapore 059413

Tel: 6536 9339

Fax: 6536 5368

E-mail: zul@juseq.com.sg