

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SMQ 8902B
 TP/AXA

*Not Authored
 Jimmy Bypaim*

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 68804739
 ATTN: Motor Claim Department

WS Ref: TP/AXA
 Claim Type: Third Party
 Accident Date: 10/09/2022
 TP Veh Reg No: SHA2398P

Estimate No: ES2300072/WS
 Date: 26 Jan 2023
 Policy No: P1066699R00
 Veh Reg No: **SMQ8902B**
 Make/Model: BMW BMW 216I GRAN
 TOURER
 Chassis No: WBA6V120805P22802
 Engine No: 41255789B38A15A
 Reg. Date: 09/12/2019

Estimate Repair Cost to Vehicle No :SMQ8902B

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	1,399.00	1 PC	1,399.00	
2 REAR BUMPER RH REFLECTOR	59.80	1 PC	59.80	
3 REAR BUMPER RH RETAINER	198.10	1 PC	198.10	
4 REAR RH REVERSE SENSOR	269.00	1 PC	269.00	
			1,925.90	
		Less 5%	96.30	1,829.61
Labour				
5 REMOVE AND REFIT REAR BUMPER, REFLECTORS, SIDE RETAINERS AND REALIGN THE SAME.	280.00	1 LA	280.00	220
6 PUTTY AND RESPRAY REAR BUMPER.	350.00	1 LA	350.00	250
7 REMOVE AND REFIT REVERSE SENSOR AND RESET SYSTEM.	80.00	1 LA	80.00	60
			710.00	710.00
			Total	S\$ 2,539.61
			Add GST @ 8%	203.17
			Total Amount Payable	S\$ 2,742.78

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey ~~before~~ after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: