

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
 #01-49 SINGAPORE 415875
 Tel: +65 64524457
 Fax: +65 64524584
 Company Reg No: 201929175W

Repair Estimate

Vehicle number: SJG8992D
 Make & Model: Honda Stream
 Chassis number: JHMRN68408S204791

Date of survey:
 Name of surveyor:
 Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Tailgate	1	\$ bt 956.00 ✓
2	Tailgate windscreen glass rubber moulding	1	\$ ne 89.00 ✓
3	Tailgate "stream" emblem	1	\$ ne 47.00 ✓
4	Tailgate centre emblem	1	\$ ne 28.00 ✓
5	Tailgate outer garnish	1	\$ na 192.00 ✓
6	Tailgate inner handle	1	\$ de 32.00 ✓
7	Tailgate inner trim board	1	\$ na 479.00 ✓
8	Tailgate lock	1	\$ bt 119.00 ✓
9	Tailgate lock catch	1	\$ x nn 45.00 ✓
10	Tailgate weatherstrip	1	\$ cut 128.00 ✓
11	Tailgate wiper motor	1	\$ x nn 452.00 ✓
12	Tailgate wiper arm	1	\$ x nn 184.00 ✓
13	Tailgate wiper blade	1	\$ x nn 73.00 ✓
14	Rear bumper	1	\$ de 812.00 ✓
15	Rear bumper towing cover	1	\$ m.s 24.00 ✓
16	Rear bumper RH lower bracket	1	\$ x nn 18.00 ✓
17	Rear bumper LH lower bracket	1	\$ 2 nn 18.00 ✓
18	Rear bumper RH side retainer	1	\$ de 22.00 ✓
19	Rear bumper LH side retainer	1	\$ de 22.00 ✓
20	RH taillamp assy	1	\$ na 446.00 ✓
21	RH taillamp panel	1	\$ x nn 164.00 ✓
22	RH taillamp lock clip	1set	\$ x nn 28.00 ✓
23	RH taillamp gasket	1	\$ x nn 25.00 ✓
24	LH taillamp assy	1	\$ na 446.00 ✓
25	LH taillamp panel	1	\$ x nn 164.00 ✓
26	LH taillamp lock clip	1set	\$ x nn 28.00 ✓
27	LH taillamp gasket	1	\$ x nn 25.00 ✓
28	End panel	1	\$ de 454.00 ✓
29	End panel inner garnish	1	\$ de 178.00 ✓
30	RH rear fender splash shield	1	\$ x nn 82.00 ✓
31	RH rear fender inner trim board	1	\$ na 382.00 ✓
32	LH rear fender splash shield	1	\$ x 82.00 ✓
33	LH rear fender inner trim board	1	\$ na 382.00 ✓
34	Rear compartment panel top RH cover	1	\$ x nn 218.00 ✓
35	Rear compartment panel top LH cover	1	\$ x nn 218.00 ✓
36	Rear compartment panel trim	1	\$ x nn 197.00 ✓
37	Exhaust silencer	1	\$ PK 637.00 ✓
38	Exhaust silencer gasket	1	\$ x nn 45.00 ✓
39	Bonnet	1	\$ R 684.00 ✓
40	Bonnet lock	1	\$ x nn 58.00 ✓

365 ✓

688 ✓

Total: \$ 2,415.00

No.	Labour and painting		Amount S\$
(Rear portion)			
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	700	\$ 1,400.00
2	Spray painting on affected areas and panels	700	\$ 1,200.00
3	Check wiring and lighting system on affected areas	30	\$ 80.00
4	Apply rust coating chemical on affected areas and panels	40	\$ 80.00
5	Remove and reinstall tailgate windscreen glass to assist repair	120	\$ 240.00
6	Remove and replace tailgate reverse camera to assist repair	30	\$ 100.00
7	Remove and replace tailgate inner mechansim to new tailgate	60	\$ 120.00
8	Remove and replace rear bumper reverse sensors to assist repair	30	\$ 100.00
9	Remove and replace rear inner trims, garnish and boards to assist repair	60	\$ 320.00
10	Remove and replace exhaust silencer and gasket to assist repair	*	\$ 180.00
(Front portion)			
11	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	300	\$ 1,000.00
12	Spray painting on affected areas and panels	400	\$ 1,000.00
13	Check wiring and lighting system on affected areas	300	\$ 80.00
14	Apply rust coating chemical on affected areas and panels	x	\$ 80.00
15	Remove and replace aircon condenser, pipes and hoses to assist repairs	100	\$ 220.00
16	Remove and replace radiator assy, hoses and fan assy to assist repairs	x	\$ 220.00
17	Refocus and adjust headlamps assy	30	\$ 80.00
			Total: \$ 6,500.00

2630

Agreed Amount: _____ (Part by Part / Lump sum)
 Working days: _____

Taylor 97495949
WP 30/11/22 @ 440
L/S resurvey after repair - 0 days
fulfill @ khantow
 - To check consistency of accident
 - To check part prices

Spare Parts: \$ 10,320.80
 Special Nett: \$ 2,415.00

LKK All hours consultants here to help the Repairer of the following:
 Total Amount: \$ 19,235.80

9746 9816

L/S - 7852.80 = 7850

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: