

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012001/TVP3Q2**Date:** 09/06/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00079112200

**Claimant Vehicle
No :** SLV8200D**Insured
Vehicle No :** SLM5801L

Date of Loss: 10/11/2022

Nature of Claim: TP

Claim
No: SNM22D208122/C01/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLV8200D**

Make & Model: PORSCHE BOXSTER, S 3.4 TIPTRONIC (A)

Engine No: 66801890

Reg. Date: 17/09/2008 (Man. Year: 2008)

Chassis No: WPOZZZ98Z8U722711

Colour: Silver

Odometer: 95320 km

Engine Capacity: 3387 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35 R19

Rear Tyre Size: 275/35 R19

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,584.79	6,347.86	11,236.93	63.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,540.00	1,040.00	2,500.00	70.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,124.79	7,387.86	13,736.93	65.03
Approved Total (Overridden) (S\$)		5,900.00		
(S\$)	21,124.79	5,900.00	15,224.79	72.07
+ GST 8.00/8.00% (S\$)	1,689.98	472.00	1,217.98	72.07
Nett Amount (S\$)	22,814.77	6,372.00	16,442.77	72.07

INSPECTION

Date of Assignment: 30/11/2022

Date Inspected: 01/12/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)

8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit

Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Jun 2023)	
Parts:	N/A	PORSCHE BOXSTER S 3.4 TIPTRONIC (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV8200D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	2,124.70 FL	*2,124.70 FL
2	1		*FRONT BUMPER RH SIDE SIGNAL LAMP	Cut	128.60 FL	*128.60 FL
3	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	92.90 FL	*- FL
4	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	92.90 FL	*- FL
5	1		*RH HEADLAMP ASSY	Not Necessary	2,672.80 FL	*- FL
6	1		*FRONT RH FENDER	Bent	1,485.55 FL	*1,485.55 FL
7	1		*FRONT RH FENDER SPLASH SHIELD	Not Necessary	273.00 FL	*- FL
8	1		*FRONT RH SPORT RIM	Cut	1,834.20 FL	*1,834.20 FL
9	1		*FRONT RH WHEEL BEARING	Not Necessary	556.00 FL	*- FL
10	1		*FRONT RH LOWER ARM	Not Necessary	873.20 FL	*- FL
11	1		*FRONT RH KNUCKLE ARM	Not Necessary	1,321.00 FL	*- FL
12	1		*FRONT RH SHOCK ABSORBER	Not Necessary	1,495.80 FL	*- FL
13	1		*FRONT RH DOOR	Not Necessary	2,334.50 FL	*- FL
14	1		*FRONT RH DOOR WEATHERSTRIP	Not Necessary	216.00 FL	*- FL
15	1		*FRONT RH DOOR INNER TRIM BOARD	Not Necessary	832.90 FL	*- FL
16	1		*FRONT RH DOOR LOCK	Not Necessary	446.70 FL	*- FL
17	1		*FRONT RH SIDE MIRROR ASSY	Cracked	1,446.80 FL	*1,446.80 FL
18	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
19	1		*FRONT RH TYRE	Not Necessary	780.00 FS	*- FS
20	1		*FRONT RH DOOR SEALANT	Not Necessary	120.00 FS	*- FS
21	1		*SET FRONT RH DOOR INNER TRIM BOARD	Not Necessary	80.00 FS	*- FS
22	1		*BRAKE FLUID	Not Necessary	100.00 FS	*- FS
					Sub Total (S\$)	19,407.55 7,049.85
					- List Item Discount on L Items 10.00/10.00% (S\$)	1,822.76 701.99
					Total Parts (S\$)	17,584.79 6,347.86

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS TO PANEL BEATING ,CUT /WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,200.00	400.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	500.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	70.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	120.00	30.00
5	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	220.00	80.00
6	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	550.00	0.00
7	REMOVE AND REPLACE FRONT RH DOOR INNER MECHANISM TO NEW DOOR	New	180.00	0.00
Gross Labour Cost (S\$)			3,540.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >