

WV D9DT

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SLV8200D

Make & Model: Porsche 987 Boxster

Chassis number: WPOZZZ98Z8U722711

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Front bumper	1	\$ 2,124.70
2	Front bumper RH side signal lamp	1	\$ 128.60
3	Front bumper RH side retainer	1	\$ 92.90
4	Front bumper LH side retainer	1	\$ 92.90
5	RH headlamp assy	1	\$ 2,672.80
6	Front RH fender	1	\$ 1,485.55
7	Front RH fender splash shield	1	\$ 273.00
8	Front RH sport rim	1	\$ 1,834.20
9	Front RH wheel bearing	1	\$ 556.00
10	Front RH lower arm	1	\$ 873.20
11	Front RH knuckle arm	1	\$ 1,321.00
12	Front RH shock absorber	1	\$ 1,495.80
13	Front RH door	1	\$ 2,334.50
14	Front RH door weatherstrip	1	\$ 216.00
15	Front RH door inner trim board	1	\$ 832.90
16	Front RH door lock	1	\$ 446.70
17	Front RH side mirror assy	1	\$ 1,446.80

\$ 18,227.55
 Parts less 10% \$ 1,822.76
 Total \$ 16,404.80

No.	Special Nett Items	Qty	Amount S\$
1	Front bumper clips	1set	\$ 100.00
2	Front RH tyre	1	\$ 780.00
3	Front RH door sealant	1	\$ 120.00
4	Front RH door inner trim board	1set	\$ 80.00
5	Brake fluid	1	\$ 100.00
Total:			\$ 1,180.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,200.00
2	Spray painting on affected areas and panels	\$ 1,200.00
3	Check wiring and lighting system on affected areas	\$ 70.00
4	Apply rust coating chemical on affected areas and panels	\$ 120.00
5	Test drive and adjust wheel alignment system	\$ 220.00
6	Remove and replace front undercarriage parts to assist repair	\$ 550.00
7	Remove and replace front RH door inner mechanism to new door	\$ 180.00

400

500

30

30

80

715 X

X

Total: \$ 3,540.00

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 16,404.80
Special Nett: \$ 1,180.00
Labour: \$ 3,540.00

Total Amount: \$ 21,124.80

Tanfah 9749549
'w' 01/12/22 @ 5pm
L/S ready after repair
Tanfah @ KKKank.com
3-4 days

- To check consistency of all
- to check part price.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: