

Vehicle Damage Assessment Report for [SHC5659G]

Estimate Created: 17/01/2023 03:53 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 05/02/2023 15:06 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Prius
Engine Type			
License Plate Number	SHC5659G	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded cost of repair at \$5537.10 with 3 days for repair	Insurlogic 5 (05/02/2023 15:05)
---	---------------------------------

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
COVER REAR BUMPER		1	485.60	-25.00 %	364.20
REINFORCEMENT SUB ASSY		1	332.70	-25.00 %	249.53
REAR BUMPER LOWER		1	22.00	-25.00 %	16.50
REAR BUMPER CTR		1	374.50	-25.00 %	280.88
COVER REAR FLOOR CTR		1	229.90	-25.00 %	172.43
COVER FRONT BUMPER		1	521.00	-25.00 %	390.75
COVER FRONT BUMPER HOLE LH		1	30.20	-25.00 %	22.65
COVER FRONT BUMPER HOLE RH		1	30.20	-25.00 %	22.65
HEADLAMP RH		1	2637.60	-25.00 %	1,978.20
REINFORCEMENT SUB ASSY FRONT		1	716.60	-25.00 %	537.45
GRILLE SUB ASSY RADIATOR		1	422.50	-25.00 %	316.88

Parts Subtotal 4,352.12

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
REAR BUMPER CLIPS		1.0	60.00	0.00 %	60.00
FRONT BUMPER CLIPS		1.0	60.00	0.00 %	60.00
FRONT NUMBER PLATE WITH MOULDING		1.0	45.00	0.00 %	45.00

Materials Subtotal 165.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
REPLACE/ REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	500.00	0.00 %	500.00
RNR REAR PARKING SENSOR	RnR	50.00	0.00 %	50.00
ELECTRICAL CHECK	RnR	30.00	0.00 %	30.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	440.00	0.00 %	440.00
Labor Rate	S\$ 50 / Hour			
			General Labor Subtotal	580.00
			Paint Labor Subtotal	440.00
			Labor Subtotal	1,020.00

Summary

Repair Cost	5,537.12
Discount(0 %)	(0.00)
	5,537.12
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	5,537.12