EavT -- REF. 03/CT122012006/7473. ASSIGNMENT 4 Q 8 524. Yr Regn. 2019, Man Veh No: From: Type: M.Car / M.Cycle / Bus / Van / Korty /. Taxi / Prime Mover Estimated Cost: OD / TP / WS/TP RES / OD RES / EVA / INV / MIV Truck / Trailer of Make: To Inspect Vehicle No: A/C: Insured / Std / Ni / NA Gueen. Colour at Workstropm/s T/Radio: Insured | Std | NI | NA 14889 Sp.Reading Eng/No: insured: FER 21 E H30130 CINO: DMCVSNA00098962201 Policy No. Claims No. SNM22D208595/C02/TANCHC Gen. Cond: Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Sum Insured Brake: Inproder / Jammed / Leaked / Burnt or (Client's Record) Modi: NID/S/Rim / STD A/Rim or Make of Veh 195/85R15 Tyre Size: (Policy Condition) BS | DUN | EXNOVA | GY | FS | LIZA | MIC | OHTSU | PIR | SUMI | Remark: The veh had commenced its repair at the time of inspection. TOYO I YOKO DT Bal. or Market Value: Front IDAC Accident Rport: Consistent? : Yes or No R/Bal. L/Bal. L/Bal. Consistent? : Yes or No GIA / PR Seen: D.O.I. 01 Est. Repairs: ____14__ days Res.: Yes or No D.O.A. 3 Val.: Yes or No Survey held at Lum Sum: Des. of Damages : Frt / Repr / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT The U/C / Chassis frame / Body Structure affected due to collision. Person Contacted: Date / Time | Action / Instruction We confirm the offer at L/S \$9,150.00 (before G\$T) with 14 working days. (red, \$35105.66, 79%) Date/Time, File Pass to? Days Of Repair: 14 : Preli. Report Survey Fee: Resurvey No. of Trip: : Final Report 1) 17/02/23 Transportation: Date/Time, File Return to? Add Fee: : Site Insp (\$ _S + RS.__SI : Interview (\$ Photos : Tech. Invs 🧐 Citizens Reprofermat: Weekend (\$ Lumin Sum / L.B.A. († 9150 TOIR



AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@kB Singapore 415875

TEL: 6702 1555

Co. Reg No.: 201500047H GST No.: 201500047H

Email: admin@autobacs.com.sg

то

: YQ9000E (CHINA TAIPING)

ATTENTION

: MOTOR CLAIMS DEPARTMENT

DATE: 30-11-2022

JOB TYPE : TP CLAIMS

VEHICLE DETAILS

ACCIDENT DETAIL

VEHICLE NO.

: YQ852Y

DATE

: 30-11-2022

MAKE / MODEL : MITSUBISHI CANTER

TIME

: 1020HRS

CLAIM DETAIL: PARTS PRICE (S\$)

	DESCRIPTION		TV	1	JNIT LIST	TOTAL LIST	1
S/N	DESCRIPTION	-	TY				
1	FRONT CABIN REAR PANEL		1	\$	4,870.13	\$ \$ \(\nu 4,870.13	-
2	FRONT CABIN REAR PANEL GLASS RUBBER MOLDING		1	\$	307.40	\$ 307.40	
3	AIR DUCT		1	\$	465.20	\$? 465.20	
4	COOLER HOUSING		1	\$	468.60	\$ 7 468.60	
5	EGR PIPE (METAL)		1	\$	865.36	\$ 7 865.36	
6	TURBO BOOST CONTROLLER		1	\$	824.20	\$ 7 824.20	
7	REAR TAILLAMP RH		1	\$	260.00	\$00.00	
8	REAR TAILLAMP LH		1	\$	260.00	\$ ₭ 260.00	
9	REAR TAILLAMP BRACKET RH		1	\$	120.00	\$ 66 - 120.00	
10	REAR TAILLAMP BRACKET LH		1	\$	120.00	\$ * 120.00	
11	REAR BOX OPEN DOOR RH		1	\$	3,500.00	\$67 -3,500.00	
12	REAR BOX OPEN DOOR LH		1	\$	3,500.00	\$66/3,500.00	
13	REAR BOX OPEN DOOR WOODEN (BEHIND) RH		1	\$	650.00	\$ 15 650.00	
14	REAR BOX OPEN DOOR WOODEN (BEHIND) LH		1	\$	650.00	\$ X 650.00	
15	REAR BOX OPEN DOOR LOCK CATCH		2	\$	380.00	\$ 6 { 760.00	
16	REAR BOX OPEN DOOR LOCK ROD		2	\$	680.00	\$6-1,360.00	
17	REAR BOX COMPANY STICKER		1	\$	1,600.00	\$14-1,600.00	00
18	REAR STAND PANEL		1	\$	1,800.00	\$ 7 1,800.00	
19	REAR CARGO BED CROSSMEMBER		3	\$	2,000.00	\$ 7 6,000.00	
20	REAR CARGO BED END PANEL		1	\$	1,800.00	\$121,800.00	
21	REAR CARGO BED CHASSIS MEMBER		2	\$	4,800.00	\$KR 9,600.00	
22	UNDER CARRIAGE U BRACKET		8	\$	250.00	\$ 7 2,000.00	
23	SLIDING DOOR RH		1	\$	3,600.00	\$ 7 3,600.00	
24	SLIDING DOOR STICKER RH		1	\$	2,000.00	\$ 2,000.00	
	•					391	

TOTAL: \$ 42,203.36 -25% \$ 10,550.84

SUB TOTAL: \$ 31,652.52 CLAIM DETAIL: PARTS S/NETT

S/N	DESCRIPTION	QTY	UNI	T S/NETT	TOTAL S/NETT	
	REAR NUMBER PLATE	1	\$	50.00	\$ ht 50.00	30
	REAR BOX DOOR STICKER '60KM/H'	1	\$	50.00	\$ New /50.00	

			_
S/NETT TOTAL	:	#REF!	
			_

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDED PORTION	DENT	\$ 6,000.00	2000.
TO SPRAY PAINTING ALL THE ACCIDENT PORION & POLISHING AFFECTED AREA		\$ 2,000.00	600
TO APPLY ANTI-RUST & TUFF KOTE		\$ 150.00	30
TO PERFORM LIGHTING & WIRING CHECK		\$ 120.00	40
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODI	ТО	\$ 350.00	Ř

LABOUR TO	TAL:	\$ 8,620.00

ESTIMATE REPORT

TOTAL PARTS:

#REF!

TOTAL LABOUR: \$

8,620.00

TOTAL AMOUNT: #REF!

Taufille 17495749/62 WP 01/12/22@420pm +aufille @llekanto.wm. 2/5 Resum after report

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- · Supplementary fem(s) must be resurveyed and is subject to that approval from insurance Company

Acknowledged by Repairer

Signature:

Date: