



Accident Reference & Bus No: **AR-2022-3800 - SBS6172Z with SMM1622B** along **03-21/22 Alexandra Rd**

Activated date: Wednesday, 30 November 2022 10:00

Activated by: Chong Kee Lim <Chongkeelim@sbstransit.com.sg>

Name of Surveyor: Taufikh <taufikh@lkkauto.com>

Company Name: LKK Auto (CTP)

Date Surveyed: 1<sup>st</sup> Dec 2022

*Estimate (before GST) for*

Stock Code	Description	Quantity	Total Material cost(S\$)
		0	\$0.00
30600021	SIGNAL LED LIGHT;AMBER	1	\$31.00
30600105	TREENAIL	2	\$2.00
(MO Number : BN2212000093 )		Sub Total S\$:	33.00

cut ✓  
nail ✓

- ☐ Parts cost: **\$33.00** ✓
- ☐ Contractor Labour cost: **\$700.00** ✓
- ☐ Workshop Labour cost: **\$188.00** ✓
- ☐ Advertisement Cost: **\$0.00**
- ☐ Repair period: **2 days**

33  
700  
188  
---  
\$921  
2 days

- ☐ Tow Cost: **\$ 0.00**
- ☐ Loss of use: **Not required by surveyor** Xun
- ☐ Overheads: **Not required by surveyor** Xun

Taufikh 97495749  
- Wps 01/12/22  
COR not confirmed with w/s.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: