

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22012013/AVCE2**Date:** 28/03/2023**REFERENCE**

Insured/Claimant:	JETSEA LOGISTICS (S) PTE LTD	Policy No:	7220111308
Date of Loss:	24/11/2022	Nature of Claim:	OD
		Claim No:	5673315250SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNH1140P		
Make & Model:	AUDI A7 SPORTBACK, 2.0 TFSI (A)	Engine No:	DKY016671
Reg. Date:	27/09/2022 (Man. Year: 2021)	Chassis No:	WAUZZZF28NN024743
Colour:	Blue	Odometer:	3207 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$340,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,914.00	4,236.48	8,677.52	67.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,432.00	2,152.00	6,280.00	74.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,346.00	6,388.48	14,957.52	70.07
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	19,746.00	4,788.48	14,957.52	75.75
+ GST 8.00/8.00% (S\$)	1,579.68	383.08	1,196.60	75.75
Nett Amount (S\$)	21,325.68	5,171.56	16,154.12	75.75

INSPECTION

Date of Assignment:	01/12/2022		
Date Inspected:	30/11/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,317.00 FS	*2,780.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	247.00 FS	*- FS
3	2		*REAR BUMPER SECURING STRIP - LH / RH	Not Necessary	96.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Not Necessary	533.00 FS	*- FS
5	1		*REAR BUMPER SPOILER CHROME TRIM - CENTER	Not Necessary	247.00 FS	*- FS
6	1		*REAR BUMPER SPOILER CHROME TRIM - LH	Not Necessary	250.00 FS	*- FS
7	1		*REAR EXHAUST CHROME TRIM - LH	Not Necessary	648.00 FS	*- FS
8	1		*REAR BUMPER SPOILER SECURING STRIP	Necessary	193.00 FS	*154.00 FS
9	2		*REAR TELEPHONE AERIAL	Necessary	183.00 FS	*72.88 FS
10	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	1,076.00 FS	*- FS
11	2		*REAR BUMPER SEAL - LH / RH	Not Necessary	32.00 FS	*- FS
12	1		*REAR BUMPER GUIDE SECTION - LH UPPER	Not Necessary	51.00 FS	*- FS
13	1		*REAR BUMPER GUIDE SECTION - LH LOWER	Not Necessary	71.00 FS	*- FS
14	2		*REAR PARKING AID SENSOR	Not Necessary	584.00 FS	*- FS
15	1		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	10.00 FS	*- FS
16	1		*SET REAR BUMPER WIRING	Not Necessary	642.00 FS	*- FS
17	1		*LED TAILLIGHT - LH OUTER	Cracked	1,537.00 FS	*1,229.60 FS
18	1		*LED TAILLIGHT TRIM - LH OUTER	Not Necessary	49.00 FS	*- FS
19	1		*LED TAILLIGHT - LH INNER	Not Necessary	3,430.00 FS	*- FS
20	1		*LED TAILLIGHT TRIM - LH INNER	Not Necessary	49.00 FS	*- FS
21	1		*AUDI EMBLEM	Not Necessary	144.00 FS	*- FS
22	1		*A7 EMBLEM	Not Necessary	104.00 FS	*- FS
23	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
24	1		*REAR LID PACKING ADHESIVE	Not Necessary	21.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	12,914.00	4,236.48
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER, TO REPAIR LHS REAR FENDER AND LHS TAILLAMP PANEL AND REAR END PANEL RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	500.00
3	TO RESPRAY REAR BUMPER, LHS REAR FENDER, REAR LID, LHS TAILLAMP PANEL AND REAR END PANEL	New	4,800.00	1,100.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			8,432.00	2,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >