

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/1062/2022/KS  
**DATE** : 28-Nov-22  
**WIP** : 52218

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/11/2022**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : M/S JETSEA LOGISTICS (S) PTE LTD  
**ADDRESS** : 9 AIRLINE ROAD  
#02-18  
SINGAPORE 819827  
**TELEPHONE** : HP +65 97525291  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7220111308  
**VEHICLE NO** : **SNH 1140 P**  
**MODEL CODE** : AUDI A7 SPORTSBACK 2.0 TFSI  
**MODEL YEAR** : 27/9/2022  
**ENGINE NO** : DKY016671  
**CHASSIS NO** : WAUZZZF28NN024743  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 24-Nov-22  
**PLACE OF ACCIDENT** : LOYANG LINK, SG  
SHELL PETROL KIOSK

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNH 1140 P**

| S/N                         | NATURE OF JOBS                                                                                                                                                                 | ESTIMATED CHARGES      | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|----------------------------|
| 1                           | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.                                                                                                              | S/N \$ 360.00          | ✓ ✓                        |
| 2                           | TO DISMANTLE AND RENEW REAR BUMPER, TO REPAIR LHS REAR FENDER AND LHS TAILLAMP PANEL AND REAR END PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ <del>2,800.00</del> | 500 ✓                      |
| 3                           | TO RESPRAY REAR BUMPER, LHS REAR FENDER, REAR LID, LHS TAILLAMP PANEL AND REAR END PANEL.                                                                                      | \$ <del>4,800.00</del> | 1100 ✓                     |
| 4                           | TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.                                                                                                                          | S/N \$ 280.00          | x                          |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                 | S/N \$ 192.00          | ✓ ✓                        |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                | <b>: \$ 8,432.00</b>   |                            |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNH 1140 P**

|                              |                                                       |     | DAMAGED PARTS & PRICES |           |
|------------------------------|-------------------------------------------------------|-----|------------------------|-----------|
| S/N                          | PARTS DESCRIPTION                                     | QTY | S/NETT                 | REMARKS   |
| 1                            | REAR BUMPER <i>Deformed</i>                           | 1   | \$ 2,317.00            | ✓ 2780    |
| 2                            | REAR BUMPER FIXING PARTS <i>new</i>                   | 1   | \$ 247.00              | +         |
| 3                            | REAR BUMPER SECURING STRIP - LH / RH <i>? nn</i>      | 2   | \$ 96.00               | ? x       |
| 4                            | REAR BUMPER SPOILER <i>new</i>                        | 1   | \$ 533.00              | x         |
| 5                            | REAR BUMPER SPOILER CHROME TRIM - CENTER <i>3 new</i> | 1   | \$ 247.00              | x         |
| 6                            | REAR BUMPER SPOILER CHROME TRIM - LH                  | 1   | \$ 250.00              | +         |
| 7                            | REAR EXHAUST CHROM TRIM - LH <i>new</i>               | 1   | \$ 648.00              | x         |
| 8                            | REAR BUMPER SPOILER SECURING STRIP <i>new nec</i>     | 1   | \$ 193.00              | ✓ 154     |
| 9                            | REAR TELEPHONE AERIAL <i>? nec</i>                    | 2   | \$ 183.00              | ? 72.88   |
| 10                           | REAR BUMPER REINFORCEMENT BEAM <i>new</i>             | 1   | \$ 1,076.00            | +         |
| 11                           | REAR BUMPER SEAL - LH / RH <i>? nn</i>                | 2   | \$ 32.00               | ?         |
| 12                           | REAR BUMPER GUIDE SECTION - LH UPPER <i>3 new</i>     | 1   | \$ 51.00               | +         |
| 13                           | REAR BUMPER GUIDE SECTION - LH LOWER                  | 1   | \$ 71.00               | +         |
| 14                           | REAR PARKING AID SENSOR <i>1 piece ? nn</i>           | 2   | \$ 584.00              | ? x       |
| 15                           | REAR PARKING AID SENSOR SEAL RING <i>new</i>          | 1   | \$ 10.00               | +         |
| 16                           | REAR BUMPER WIRING SET <i>new</i>                     | 1   | \$ 642.00              | +         |
| 17                           | LED TAILLIGHT - LH OUTER <i>could</i>                 | 1   | \$ 1,537.00            | ✓ 1229.60 |
| 18                           | LED TAILLIGHT TRIM - LH OUTER <i>new</i>              | 1   | \$ 49.00               | +         |
| 19                           | LED TAILLIGHT - LH INNER <i>new</i>                   | 1   | \$ 3,430.00            | +         |
| 20                           | LED TAILLIGHT TRIM - LH INNER <i>new</i>              | 1   | \$ 49.00               | +         |
| <b>SUB TOTAL SPARE PARTS</b> |                                                       | :   | <b>\$ 12,245.00</b>    |           |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNH 1140 P**

|                             |                                      |     | DAMAGED PARTS & PRICES |         |
|-----------------------------|--------------------------------------|-----|------------------------|---------|
| S/N                         | PARTS DESCRIPTION                    | QTY | S/NETT                 | REMARKS |
| 21                          | REAR LID PACKING ADHESIVE <i>new</i> | 1   | \$ 21.00               | +       |
| 22                          | AUDI EMBLEM <i>new</i>               | 1   | \$ 144.00              | +       |
| 23                          | "A7" EMBLEM                          | 1   | \$ 104.00              | +       |
| 24                          | SUNDRIES <i>nn</i>                   | 1   | \$ 400.00              | X       |
| <b>TOTAL SPARE PARTS</b>    |                                      | :   | <b>\$ 12,914.00</b>    |         |
| <b>TOTAL LABOUR CHARGES</b> |                                      | :   | <b>\$ 8,432.00</b>     |         |
| <b>GRAND TOTAL</b>          |                                      | :   | <b>\$ 21,346.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan  
SURVEYED DATE : 30/11/22  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : not authorized, 04 days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT