

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01067/2022/EQ
DATE : 30-Nov-22
WIP : 52807

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/11/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LAI WEIXIONG
ADDRESS : 23 ANCHORVALE CRESCENT
#16-26
SINGAPORE 544655
TELEPHONE : HP +65 92315678
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700063086-05
VEHICLE NO : **SLS 8512 U**
MODEL CODE : AUDI Q2 1.0 TFSI S-TRONIC
MODEL YEAR : 9/10/2017
ENGINE NO : CHZ 401057
CHASSIS NO : WAUZZZGAXHA055607
MILEAGE : 76,131
DATE IN : 29-Nov-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Nov-22
PLACE OF ACCIDENT : 23 ANCHORVALE CRES, SINGAPORE 544655
CONDO CARPARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 8512 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280 280
2	TO DISMANTLE AND RENEW RHS FRONT DOOR. TO REPAIR RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,800.00	500 500
3	TO RESPRAY RHS FRONT DOOR, DOOR HANDLE, RHS REAR DOOR AND RHS WING MIRROR COVER.	\$ 3,000.00	Door 550 Handle 100 Wing Mirror 150. 800
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	192
TOTAL LABOUR CHARGES		: \$ <u>5,392.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 8512 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - RH <i>Dented</i>	1	\$ 2,962.00	✓ 2369.6
2	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 98.00	+ X
3	FRONT DOOR CATCH - RH <i>? X</i>	1	\$ 134.00	? X condition
4	FRONT DOOR HANDLE - RH <i>cut</i>	1	\$ 398.00	✓ 318
5	FRONT DOOR HANDLE CAP - RH <i>cut</i>	1	\$ 62.00	✓ 48.96
6	FRONT DOOR LOCK CYLINDER WITH HOUSING - RH <i>new</i>	1	\$ 564.00	+ X
7	FRONT DOOR SLIDE VALVE - RH <i>new</i>	1	\$ 25.00	+ X
8	FRONT DOOR HANDLE SENSOR - RH <i>new</i>	1	\$ 255.00	+ X
9	FRONT DOOR UNDERLAY - RH <i>new</i>	1	\$ 6.00	+ X
10	REAR DOOR UNDERLAY - RH <i>new</i>	1	\$ 7.00	+ X
11	FRONT DOOR MOUNTING BAR - RH <i>new</i>	1	\$ 178.00	+ X
12	FRONT DOOR BOWDEN CABLE <i>new</i>	1	\$ 58.00	+ X
13	FRONT EXTERIOR WING MIRROR MOUNTING - RH <i>new</i> ✓	1	\$ 571.00	✓ 456.8 condition
14	FRONT WING MIRROR CAP - RH <i>cut</i>	1	\$ 203.00	✓ 162.4
15	FRONT WING MIRROR GLASS - RH <i>new</i>	1	\$ 325.00	+ X
16	FRONT DOOR COVER - RH <i>cut</i>	1	\$ 270.00	✓ 216
17	FRONT TYRE PRESSURE DATA PLATE <i>new</i> X	1	\$ 34.00	+ X condition
18	REAR DOOR COVER - RH <i>new</i>	1	\$ 238.00	+ X
19	SUNDRIES <i>? ✓</i>		\$ 400.00	? ✓ 15.36 condition
TOTAL SPARE PARTS		:	\$ 6,788.00	
TOTAL LABOUR CHARGES		:	\$ 5,392.00	
GRAND TOTAL		:	\$ 12,180.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King
SURVEYED DATE : 30/11/22
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Hui Rong

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/01067/2022/EQ

14-Dec-22

CHANG


1 of 1

SLS 8512 U

AUDI Q2 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT WINDOW APERTURE SEAL - RH <i>Rehd</i> 1	\$ 151.00	✓ 120.4
GRAND TOTAL		\$ 151.00	

For Premium Automobiles Pte Ltd


Authorised Signature

Adrian Ling
Remmyed S/S

Car-in 5/12/12

wp: 52807

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Benz:



AIG - Adnan

- 3 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLS 8512 U

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - RH <i>Dented</i>	1	\$ 2,962.00	✓
2	FRONT DOOR ATTACHMENT PARTS <i>new</i>	1	\$ 98.00	+
3	FRONT DOOR CATCH - RH <i>?</i>	1	\$ 134.00	?
4	FRONT DOOR HANDLE - RH <i>cut</i>	1	\$ 398.00	✓
5	FRONT DOOR HANDLE CAP - RH <i>cut</i>	1	\$ 62.00	✓
6	FRONT DOOR LOCK CYLINDER WITH HOUSING - RH <i>new</i>	1	\$ 564.00	+
7	FRONT DOOR SLIDE VALVE - RH <i>new</i>	1	\$ 25.00	+
8	FRONT DOOR HANDLE SENSOR - RH <i>new</i>	1	\$ 255.00	+
9	FRONT DOOR UNDERLAY - RH <i>new</i>	1	\$ 6.00	+
10	REAR DOOR UNDERLAY - RH <i>new</i>	1	\$ 7.00	+
11	FRONT DOOR MOUNTING BAR - RH <i>new</i>	1	\$ 178.00	x
12	FRONT DOOR BOWDEN CABLE <i>new</i>	1	\$ 58.00	+
13	FRONT EXTERIOR WING MIRROR MOUNTING - RH <i>cut</i>	1	\$ 571.00	✓ <i>h/s</i>
14	FRONT WING MIRROR CAP - RH <i>cut</i>	1	\$ 203.00	✓
15	FRONT WING MIRROR GLASS - RH <i>new</i>	1	\$ 325.00	+
16	FRONT DOOR COVER - RH <i>cut</i>	1	\$ 270.00	✓
17	FRONT TYRE PRESSURE DATA PLATE <i>new</i>	1	\$ 34.00	✓
18	REAR DOOR COVER - RH <i>new</i>	1	\$ 238.00	+
19	SUNDRIES <i>?</i>		\$ 400.00	?
TOTAL SPARE PARTS			\$ 6,788.00	
TOTAL LABOUR CHARGES			\$ 5,392.00	
GRAND TOTAL			\$ 12,180.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.