



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 2975T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	SUPPLY AND INSTALL NEW SET OF SS180M TMA.		65,000.00	30,000.00
	LESS: GOOD WILL DISCOUNT		-5,000.00	-
			60,000.00	30,000.00
	GRAND TOTAL		60,000.00	30,000.00
RECOMMENDED COST OF REPAIRS				30,000.00

Report Ref No. CS3/LPC22008063/Sqy3e2-1

NOTE: OUR RECOMMENDED TMA COST IS SUBJECTED TO REVIEW UPON RECEIPT OF ADDITIONAL DOCUMENTS THAT MAY BE FORTH COMING.

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.