



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

ATTN: MOTOR CLAIMS DEPT

VEHICLE NO. : FBL5867X
MAKE/MODEL : BMW / R NINET

NO. : 42243

DATE : 30/11/2022
CLAIM NO. : 12051
POLICY NO. : MC/00568819/03
FROM : RAYMOND

*Not Authorised
her
1/55
5 days.
change the thing -
62563561
1/11/22*

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER HANDLE P/N: 75783 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$72.80	CU7 72.80
2	BELLY PAN WUNDERLICH P/N: 75799 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$588.00	CU7 588.00
3	BOLT FOOTREST 32MM P/N: 75786 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$15.40	RM/ o/s CU7 30.80
4	BOLT STUD P/N: 60717 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$7.00	? 28.00
5	COVER AIR SNORKEL REAR P/N: 75785 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$476.00	11 476.00 X
6	COVER CYLINDER HEAD P/N: 55767 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$660.73	CU7 660.73
7	COVER FOR CYLINDER LOWER LH P/N: 75776 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$61.60	? 61.60
8	COVER LIG OIL P/N: 75798 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.60	mer 12.60
9	COVER RETAINER PANEL LH P/N: 75794 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$39.20	Dye? 39.20

*42243 *

bizSAFE₃



Address: No.6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) + 65 6284 2969, (Accounts) + 65 6281 6759

CERT NO: 2000-1-0183
ISO 9001:2015

S/N ^o	Description	Action	Qty	Unit Price	Amount
10	COVER SPARK PLUG LH P/N: 75781 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.40	cut? 36.40
11	COVER SPARK PLUG RH P/N: 75792 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$36.40	cut 36.40
12	COVER VALVE GRANIT P/N: 64857 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$550.20	cut 550.20 ?
13	CYLINDER HEAD GUARD LH RH WUNDERLICH P/N: 75801 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$630.00	cut 630.00
14	CYLINDER HEAD LH P/N: 60731 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,466.80	? 2,466.80
15	DIAGNOSTIC (ECU/ABS/FI) P/N: 53340 - (REPORTED BY MECHANIC)		1.00	\$84.00	? 84.00
16	FOOTREST REAR RH P/N: 75793 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$166.60	cut 166.60
17	GASKET CYLINDER HEAD P/N: 60714 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$130.20	? 260.40
18	GASKET CYLINDER HEAD COVER P/N: 75778 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$233.80	? 233.80
19	GEARBOX GUARD WUNDERLICH P/N: 75800 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$280.00	? 280.00
20	GUM GASKET (BMW) 35ML P/N: 61617 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$74.20	? 74.20
21	HEAD CYLINDER BLOCK RH P/N: 64862 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,466.80	cut 2,466.80 X
22	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	24.00	\$63.00	? 1,512.00
23	LAMP SIGNAL REAR RH P/N: 75788 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$99.40	320 99.40
24	LAMP TAIL REAR LED P/N: 75779 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$260.40	cut 260.40

*42243 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	LEVER BRAKE P/N: 75796 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$211.40	211.40
26	LEVER CLUTCH P/N: 75795 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$211.40	211.40
27	MIRROR LH P/N: 75789 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$207.20	207.20
28	MIRROR RH P/N: 75787 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$207.20	207.20
29	OIL ENGINE (MOBIL) ADVANCE RACING 1 10/40 P/N: 72811 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$36.40	145.60
30	O-RING (27X3.2) OIL FILTER P/N: 57385 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	7.00
31	O-RING 10.5X1.5 P/N: 75777 - (REPORTED BY MECHANIC)	REPLACE	8.00	\$5.60	44.80
32	PAD SHIM 4.6 P/N: 75782 - (REPORTED BY MECHANIC)	REPLACE	8.00	\$19.60	156.80
33	PEDAL BRAKE P/N: 75784 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$303.80	303.80
34	PLATE NUMBER REAR (BMW PERFORMANCE) P/N: 72766 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
35	SCREW WITH BUSH P/N: 55765 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$39.20	156.80
36	TRANSPORT CHARGES (MOTORCYCLE) CLASS 2 P/N: 45836 - BIKE TOWED BACK TO BHH		1.00	\$77.00	77.00
37	TUBE INNER 5.50/6.00-17 P/N: 73574 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$56.00	56.00
38	TWIST PROTECTION LH P/N: 75790 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$58.80	58.80
39	TWIST PROTECTION RH P/N: 75797 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$56.00	56.00

*42243 *

bizSAFE



S/N	Description	Action	Qty	Unit Price	Amount
40	TYRE 180/55-17 (MITAS) SPORT FORCE + P/N: 75802 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$261.80	261.80
41	VALVE EXHAUST P/N: 60720 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$281.40	1,125.60
42	VALVE INTAKE P/N: 75791 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$197.40	789.60
43	VALVE SEAL RING KIT P/N: 75780 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$200.20	200.20

SUB TOTAL

\$15,439.13

GST @ 7 %

\$1,080.74

GRAND TOTAL (SGD)

\$16,519.87

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repair/painting.
- To display damaged parts/panels for survey.
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

*42243 *

bizSAFE₃