



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNF 3882D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER TOP	TO REPAIR SEE LABOUR	1,405.00	-
1	REAR BUMPER BOTTOM	DEFORMED	1,380.00	745.00
1	REAR BUMPER RETAINER LH	NOT NECESSARY	87.00	-
1	REAR BUMPER RETAINER RH	NOT NECESSARY	87.00	-
1	REAR BUMPER BRACKET LH	NOT NECESSARY	87.00	-
1	REAR BUMPER BRACKET RH	NOT NECESSARY	87.00	-
1	REAR REFLECTOR LH	NOT NECESSARY	198.00	-
1	REAR REFLECTOR RH	NOT NECESSARY	198.00	-
1	REAR REFLECTOR CENTRE	NOT NECESSARY	425.00	-
1	REAR BUMPER LOWER GARNISH	NOT NECESSARY	769.00	-
1	REAR BUMPER INNER BRACKET LH	NOT NECESSARY	259.00	-
1	REAR BUMPER INNER BRACKET RH	NOT NECESSARY	259.00	-
1	REAR END PANEL	NOT NECESSARY	852.00	-
1	REAR END PANEL REINFORCEMENT	NOT NECESSARY	565.00	-
	LESS 10% DISCOUNT		-665.80	-74.50
			5,992.20	670.50
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	90.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	50.00	-
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	50.00	-
1	REVERSE SENSOR (SN)	SERVICEABLE	480.00	-
1	JOINT SEALANT (SN)	NOT NECESSARY	120.00	-
			790.00	-
<u>LABOUR</u>				
	CHECK REAR WIRING AND LIGHTING SYSTEM.	NOT NECESSARY	100.00	-
	REMOVE AND RENEW REAR REVERSE SENSOR.		120.00	50.00
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.	NOT NECESSARY	150.00	-
	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER TOP.		600.00	250.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING ON AFFECTED AREAS.	NOT NECESSARY	600.00	200.00
	APPLY ANTI RUST ON AFFECTED AREAS.		100.00	-
			1,670.00	500.00
GRAND TOTAL			8,452.20	1,170.50
RECOMMENDED COST OF REPAIRS				1,170.50

Report Ref No. CS/SMO22012021/Uny3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.