

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 02 Dec 2022

## **Preliminary Advice**

Vehicle No	: XE3164E	Accident Date	: 23/11/2022
Make	: MITSUBISHI FUSO	Policy No.	: SPCM1000000828
Assignment Date	: 01/12/2022	Excess	: S\$1,500.00
Date of Inspection	: 01/12/2022	Est. Duration of Repair	: 12
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	102,997.40
Revised Amount	:S\$	37,701.40
Check Items (Estimated)	:S\$	53,329.50
Total	:S\$	91,030.90

Lump Sum Repair	:S\$	
-----------------	------	--

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	89,000.00
COE / PARF Rebate	:S\$	6,335.00
Salvage Value	:S\$	
Margin for Repair	:S\$	82,665.00

## **Remarks**

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : The repairer able to repair the vehicle not more than Lump Sum \$82,000.00.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.