



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22012026/Kvy3q2 Date: 29/05/2023	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKJ 9992U	Veh. Inspected	SNA 8H	
Policy No.	P10685775R00	Coverage (\$)	0.00	
Claim No.	C10018880/CD	Excess (\$)	0.00	
Assign From	MAYBIE CHUA	Assign Date	01/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLC300 (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	W1N2533842F804165	Colour	WHITE	
Odometer	24008 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R19	PIRELLI	8 mm	
L/H Front Tyre	235/55 R19	PIRELLI	8 mm	
R/H Rear Tyre	255/50 R19	PIRELLI	8 mm	
L/H Rear Tyre	255/50 R19	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/11/2022	Inspection Date	05/12/2022	
Survey held at	TROPICAL SUCCESS AUTO CARE BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	