

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 609533
TEL: 6481 7773 / 6481 1403 FAX: 6484 4978
E-mail: ttec303@singnet.com.sg

M/s: Auto & General Insurance (Singapore) Pte Ltd
190, Clemenceau Avenue, #03-01,
Singapore Shopping Centre,
Singapore 239924

Estimate bill: TT 42 / 22 / TP / WT

Registration No: SNA8H

Attn: Motor Claims Department
Tel: 6221 2111
Fax: 6725 0611

Make / model: MB GLC300 (253)

Mileage:

Date: 02 / 12 / 2022

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SKJ9992U AND SNA8H ALONG
CTE ON 24 NOVEMBER 2022 AT ABOUT 1820HRS.

1pc	Rear bumper	1533.20	\$	1,619.00	✓
6pcs	Rear bumper parking sensor		\$	1,368.00	X
6pcs	Rear bumper parking sensor seal ring		(Each \$228.00)	102.00	X
1pc	Rear bumper lip	775	(Each \$17.00)	1,241.00	✓
1pc	Rear bumper lip chrome trimming (LH)		\$	324.00	✓
1pc	Rear bumper lip chrome trimming (Centre)		\$	243.00	✓
1pc	Rear bumper sponge		\$	216.00	✓
1pc	Rear bumper frame		\$	338.00	X
	Sub A total:		\$	5,451.00	
	Less 10% discount:		\$	545.10	
	A total:		\$	4,905.90	

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear bumper, rear bumper parking sensors, rear bumper parking sensor seal rings, rear bumper lip, rear bumper lip chrome trimming (LH), rear bumper lip chrome trimming (Centre), rear bumper sponge, rear bumper frame.

Heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Aligment jack.

Diagnostic and reset rear bumper parktronic sensor fault error by HHT

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear end panel, rear bumper, rear bumper parking sensors.

Grand final amount:

\$	600.00	2501
\$	100.00	601
\$	80.00	151
\$	200.00	X
\$	1,000.00	2801
\$	6,885.90	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

Not Authorized
Recovery B4 paint
2- days

2682-38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: