

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 417883

VEHICLE DETAILS

VEHICLE NO : SGD8448K
VEHICLE MODEL : TOYOTA ALTIS
CHASSIS NO : MR053REH604595849

TP SPF.

VERON.

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Del</i>	1	\$ 545.90	\$ 545.90 ✓
2	REAR BUMPER SIDE HOLDER LH <i>Acu</i>	1	\$ 54.50	\$ 54.50 +
3	REAR BUMPER RELFECTOR LH <i>cut</i>	1	\$ 74.80	\$ 74.80 ✓
4	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 395.10	\$ 395.10 ✓
5	REAR END PANEL <i>Rys</i>	1	\$ 695.30	\$ 695.30 +

TOTAL PRICE: \$ 1,765.60
LESS 25% \$ 441.40
SUB TOTAL PRICE: \$ 1,324.20

1015.80

761.85

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>Acu</i>	1 SET	\$ 30.00	\$ 30.00 ✓
2	REVERSE SENSOR <i>Acu</i>	1 SET	\$ 280.00	\$ 280.00 +
3	REAR END PANEL SEALANT <i>Acu</i>	1 SET	\$ 60.00	\$ 60.00 +

TOTAL : \$ 370.00

30

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 600.00	<i>250</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 600.00	<i>250.</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>x</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
6	TO REMOVE UPHOLSTERY	\$ 150.00	<i>x</i>	

TOTAL: \$ 1,650.00

580

ESTIMATE REPORT

TOTAL PARTS COST: \$ 1,694.20
TOTAL LABOUR COST: \$ 1,650.00
TOTAL REPAIR COST: \$ 3,344.20

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

total: 1371.85

4/s: 1.1K.

03 Days

1.1K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: