



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22012029/Uwy3m4	
			Date: 19/01/2023	
			Code: UOI2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	Insured Veh.		Veh. Inspected	SMH 5353C
	Policy No.	DHOM120049332002	Coverage (\$)	0.00
	Claim No.	M12D00112212	Excess (\$)	750.00
	Assign From	KATIE LEE	Assign Date	01/12/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA TANK (A)	c.c	996
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	M900A0182107	Colour	RED
	Odometer	81890 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	165/65 R14	FALKEN	6 mm
	L/H Front Tyre	165/65 R14	FALKEN	6 mm
	R/H Rear Tyre	165/65 R14	FALKEN	6 mm
	L/H Rear Tyre	165/65 R14	FALKEN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	29/11/2022	Inspection Date	02/12/2022
	Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE MARKET VALUE IS S\$65,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	