



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22012031/Kvy3e2	
			Date: 20/02/2023	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SMA 5017K	Veh. Inspected	SHD 7119E
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2204390/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	01/12/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	HYUNDAI I40 (A)	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KMHLB41UMHU096242	Colour	LIGHT BLUE
	Odometer	707248 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	WEST LAKE	7 mm
	L/H Front Tyre	205/60 R16	WEST LAKE	7 mm
	R/H Rear Tyre	205/60 R16	WEST LAKE	8 mm
	L/H Rear Tyre	205/60 R16	WEST LAKE	8 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	30/11/2022	Inspection Date	01/12/2022
	Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate		
	Repairer	BIFROST AUTO PTE LTD		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	