

ASS. REC. BY:

REF:

LPC / 220120361KP

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3-6 days Res.: Yes or NoLum Sum: 1.8.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLE 3561J Yr Regn: 07.16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA WagonMake: Mer GLC250 c.c. 1991Colour: Am. Grey A/C: Insured / Std / NI / NASp. Reading: 08181 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDC 25394621-084676Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD / Rlm or

Tyre Size: F: _____

R: 235/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 30/11/22 D.O.I. 12/12/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Shirley said owner insist part by part.

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

S - RS, SI

F. Invs

Others

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

MBM WHEELPOWER PTE. LTD.

YOUR REF.: XD5135G

OUR REF.: SLE3561J

TO: LONPAC INSURANCE

CC: MOTOR CLAIMS DEPARTMENT

FAX:

Not Withheld
Attn: Shirley
Presumably After Repair
Part by Part
5-6 days



DATE: 5/12/2022
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: MERCEDES GLC250 4MATIC
CHASSIS NO.: WDC2539462F084676
ENGINE NO.: 27492030655101
YEAR MADE: 2016
ACCIDENT DATE: 30 November 2022

ESTIMATE FOR VEHICLE NO.: SLE3561J

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAILGATE		1	\$ <i>B1</i> ✓ 3,050.00
2	TAILGATE WEATHERSTRIP		1	\$ <i>B2</i> X 480.00
3	TAILGATE HINGE LH		1	\$ <i>N</i> X 240.00
4	TAILGATE HINGE RH		1	\$ <i>N</i> X 240.00
5	TAILGATE LOCK		1	\$ <i>N</i> X 300.00
6	TAILGATE MERCEDES LOGO		1	\$ <i>N</i> ✓ 60.00
7	TAILGATE "GLC 250" EMBLEM		1	\$ <i>N</i> ✓ 100.00
8	TAILGATE "4 MATIC" EMBLEM		1	\$ <i>N</i> ✓ 140.00
9	TAILGATE LAMP LH		1	\$ <i>B2</i> X 550.00
10	TAILGATE LAMP RH		1	\$ <i>B2</i> X 550.00
11	TAIL LAMP LH		1	\$ <i>B2</i> X 580.00
12	TAIL LAMP RH		1 1	\$ <i>B2</i> X 580.00
13	REAR BUMPER		1	\$ <i>B1</i> ✓ 950.00
14	REAR BUMPER TOWING COVER		1	\$ <i>B2</i> X 75.00
15	REAR BUMPER RETAINER LH		1	\$ <i>B2</i> X 100.00
16	REAR BUMPER RETAINER RH		1	\$ <i>B2</i> X 100.00
17	REAR BUMPER REINFORCEMENT		1	\$? 840.00
18	REAR BUMPER SENSOR		1	\$ <i>B2</i> X 1,000.00
19	REAR BUMPER CLIP		1	\$ <i>N</i> ✓ 80.00
20	REAR BUMPER REFLECTOR LH		1	\$ <i>B2</i> X 50.00
21	REAR BUMPER REFLECTOR RH		1	\$ <i>B2</i> X 50.00
22	REAR BUMPER LOWER DIFFUSER		1	\$? 750.00
23	REAR BUMPER LOWER DIFFUSER TRIM		1	\$? 450.00
24	END PANEL		1	\$ <i>N</i> ? 1,700.00
25	END PANEL TOP GARNISH		1	\$ <i>B2</i> X 390.00
TOTAL:				\$ 13,405.00
LESS 10%:				\$ (1,340.50)
PARTS TOTAL:				\$ 12,064.50

MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-02

SIN MING AUTOCITY

T 6262 8888 F 6452 5333

COMPANY REG. NO.: 200204110W

SPECIAL NETT

NUMBER PLATE & HOLDER
BODY SEALANT

1	\$	<i>Sm</i>	X	50.00
1	\$	<i>Nh</i>	X	50.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	<i>?</i>	1,600.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	<i>20h</i>	80.00
TO REMOVE & REFIT ALL SENSOR	\$	<i>60h</i>	150.00
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	<i>?</i>	250.00
TO APPLY ANTI-RUST	\$	<i>30h</i>	80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	<i>660h</i>	1,600.00
TOTAL:	\$		15,924.50
7% GST:	\$		1,114.72
GRAND TOTAL:	\$		17,039.22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/11/2022 18:34 (SGT)
Reported by	Both
Date of Accident	30/11/2022 12:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	SLE EXITING TOWARDS WOODLANDS AVE 12
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLE3561J

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAY CHUNG HONG
NRIC No	S6848881H
Email Address	Edwardtay68@gmail.com
Mobile Phone No	(Phone) +65-81189119
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	GLC250 4MATIC AMG LINE (R19 LED)
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1991


INSURANCE COMPANY

Name of Insurance Company	Singapore Life Ltd
Policy Number / Cover Note Number	10847549


DRIVER

Name of Driver	TAY CHUNG HONG
NRIC No	S6848881H
Date Of Birth	28/12/1968
Occupation	Indoor

ACCIDENT



ROADLANDS



A: VLE 30613

B: XDB 256

BLE RUP 040


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed By Reporting Officer
Wong Jun Keat

Witnessed by Reporting Centre
Personnel