



1 Defu Lane 6 Singapore 539365
Tel: 68585151 (24 Hours) Fax: 68580877
GST Regn. No. : M2-8922054-2

Date : 01 December 2022

陳林摩 TAN LIM
 1 Defu Lan
 Tel: 68585151 (2
 GST Regn
 Date
 7 days
 when the the up

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	tailgate lid	\$ 2,580.00
02	1 pc	tailgate lid Harrier badge	\$ 110.00
03	1 pc	tailgate lid lock	\$ 974.00
04	1 pc	tailgate lid weatherstrip	\$ 442.00
05	1 pc	n/s tailgate lid reflector	\$ 498.00
06	1 pc	tailgate lid inner trimboard	\$ 578.00
07	1 pc	tailgate lid keyless sensor	\$ 100.00
08	1 pc	rear windscreen weatherstrip	\$ 180.60
09	1 pc	rear bumper	\$ 1,415.00
10	2 ps	rear bumper side retainer @ \$85.00	\$ 170.00
11	2 ps	rear bumper side holder @ \$25.00	\$ 50.00
12	10 ps	rear bumper clips @ \$5.00	\$ 50.00
13	1 pc	rear bumper lower	\$ 455.00
14	1 pc	rear bumper lower reflector n/s	\$ 57.60
15	1 pc	rear bumper sponge	\$ 125.00
16	1 pc	rear bumper end splashhold cover	\$ 75.00
17	1 pc	n/s rear lamp	\$ 765.00
18	2 ps	n/s rear lamp clip holder @ \$4.50	\$ 9.00
19	1 pc	rear end panel	\$ 625.00
20	1 pc	rear end panel inner trim	\$ 445.00
21	4 ps	rear end panel inner trim clips @ \$4.50	\$ 18.00
22	1 pc	n/s rocker panel garnish	\$ 550.00
23	1 pc	n/s rear fender	\$ 1,446.30
24	1 pc	n/s rear fender inner cowling	\$ 522.50
25	10 ps	n/s rear fender inner cowling clips @ \$5.00	\$ 50.00
26	1 pc	n/s rear fender wind deflector	\$ 89.80
27	1 pc	n/s front door	\$ 1,489.00
28	1 pc	n/s front door hinge - top	\$ 88.00
29	1 pc	n/s front door hinge - bottom	\$ 88.00
30	1 pc	n/s front door chrome moulding	\$ 120.00
31	1 pc	n/s front door outer moulding	\$ 210.00
32	1 pc	n/s rear door	\$ 1,396.00
33	1 pc	n/s rear door chrome moulding	\$ 120.00
		Less 25 %	\$ 15,891.80
			\$ 3,972.95
			\$ 11,918.85
		<u>SPECIAL NETT ITEMS</u>	
34	1 pc	n/s rear fender quater glass sealant	\$ 50.00
35	1 tube	rear windscreen glass sealant	\$ 180.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SKB37D
Date of Accident : 30 November 2022

Mr Gaurav Gour

Date : 01 December 2022

Estimate To Repair SLW1718T - Toyota Harrier G Grade
Chassis No : JTEKB3GH90J001220

S/No	Quantity	Description	Amount
<u>SPECIAL NETT ITEMS</u>			
36	1 pc	rear windscreen glas inner sponge seal	\$ 100.00
37	1 pc	rear licence plate	\$ 50.00
38	1 pc	backoff camera len	\$ 400.00
39	1 set	rear bumper parking sensor	\$ 450.00
			\$ 1,230.00
<u>LABOUR & MISC. CHARGES</u>			
01		To remove and refit rear windscreen glass.	\$ 140.00
02		To rust-proofing of the affected areas.	\$ 500.00
03		To check electrical lighting concerned.	\$ 120.00
04		To transfer of n/s both door fittings and perform water seepage test.	\$ 200.00
05		To reinstall of rear bumper parking sensor.	\$ 150.00
06		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00
07		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 120.00
08		To remove and refit n/s rear fender quarter glass.	\$ 150.00
09		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,600.00
10		Putty and spray painting of the affected portion.	\$ 1,600.00
			\$ 4,730.00
		Total	\$ 17,878.85
		Rear air vent inner garnish n/s	2w / \$ 108.50
		Rear tools tray n/s	one \$ 345.20
		tail lay housing panel n/s	2 \$ 408.10
		Rear damper, susp tower	left / twi \$ 785.10

P- 11172.1
252
\$ 379.07
310
2560