



**Auto 101 LLP**

No. 2 Yishun Industrial St 1  
 Northpoint Bizhub, #02-01  
 Singapore 768159  
 Tel: 67545101

DATE: 18-12-2022

REPAIR ESTIMATE

VEHICLE: SLF4315S  
 MODEL: Kia Carens ✓

S/n	Description of part	Qty	Estimate	
1	Front bumper	1	695.00	CRC ✓
2	Front bumper clip - set	1	30.00	NEC ✓
3	Front bumper side retainer LH	1	47.00	?
4	Front bumper body kit	1	665.00	SCR CRA
5	Front headlamp LH	1	1668.00	SCR 904 CUT
6	Fog lamp LH	1	226.00	x
7	Fog lamp cover LH	1	243.00	x
8	Front grille uppwe	1	398.00	SCR 256 CRA
9	Front grille lower	1	125.00	x
10	Front logo	1	35.00	NEC ✓
11	Front bumper reinforcement	1	198.00	?
<b>Sub-total 1</b>			<b>4,330.00</b>	
<b>Less 10% discount</b>			<b>3,897.00</b>	
12	Number plate	1	50.00	BT
13	Front parking sensor	1	300.00	DAG 200
<b>Sub-total 2</b>			<b>350.00</b>	
<b>Labour</b>				
14	To straighten and panel beating front frame member. To remove and refit above parts.	1	800.00	400
15	To putty, re-spray painting and polish rear affected areas.	1	700.00	400
16	To rust proof affected rear areas.	1	50.00	x
17	To check and rectify wiring system	1	60.00	30
<b>Labour total</b>			<b>1,610.00</b>	
<b>Parts &amp; Labour total</b>			<b>5,507.00</b>	✓

04 days LIS

Akid 8700 5631

18/04/23 1518