

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	18:16HRS
ACCIDENT DATE	29-Nov-22
BUS CAPTAIN NAME	LIM HOCK BENG
THIRD PARTY CLAIM AGAINST	Liberty Insurance Pte Ltd

BUS REGISTRATION NUMBER	SMB3033X
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	REAR WINDSCREEN GLASS <i>bro</i> ✓	1	\$ 960.00
2	INSCRIPTION LOGO (MAN REAR WORDS) <i>me</i> ✓	1	\$ 89.18
3	GIVE WAY STICKER <i>me</i> ✓	1	\$ 40.00
4	"SG BUS" STICKER (S) <i>me</i> ✓	1	\$ 100.00
5	"TOWER TRANSIT" STICKER (S) <i>me</i> ✓	1	\$ 40.00
6	SIKAFLEX BLACK (SEALANT) <i>me</i> ✓	4	\$ 128.00
7	60KM/HR STICKER <i>me</i> ✓	1	\$ 6.00

7% GST \$ 95.42
PARTS TOTAL COST \$ 1,458.60

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- ITEM NOS. 1 - 7	\$ 1,950.00
TO REMOVE & INSTALL PARTS SO AS TO PERFORM REPAIR WORKS :- - REAR ENGINE DOOR - REAR BUMPER	\$ 1,300.00
SPRAY PAINTING :- - REAR ENGINE DOOR - REAR BUMPER	\$ 1,280.00

SPRAY PAINTING \$640 PER PANEL
 LABOUR CHARGES \$650 PER DAY

7% GST \$ 317.10
LABOUR TOTAL COST \$ 4,847.10

ESTIMATED ACCIDENT REPAIR COST



SECTION 3 : RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

		DATE IN	29-Nov-2022
		DATE & TIME SURVEY	
		DATE OUT	
		TOTAL NUMBER OF DAYS	6
BUS TYPE (SD / DD)	SD	LOSS OF USE COST	
		\$1,800.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rahul
Hr 90010018

4 days

02/12/22 @ 1410

Resurvey after repair

SUMMARY	
SECTION NO.	COST
1	\$ 1,458.60
2	\$ 4,847.10
3	-
4	\$ 1,800.00
TOTAL	\$ 8,105.70