

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22006259/KPA3Q2-1**Date:** 16/01/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000770563
Claimant Vehicle No :	GBD6960U	Insured Vehicle No :	SMS5677K
Date of Loss:	20/06/2022	Nature of Claim:	TP
		Claim No:	202222005352KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD6960U	Engine No:	K9KC400D054222
Make & Model:	NISSAN NV200, 1.5 (A)	Chassis No:	VSKYBAM20Z0092730
Reg. Date:	18/03/2015 (Man. Year: 2014)	Odometer:	98833 km
Colour:	White		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Davanti 6 mm	Rear Left Side:	Goodyear 9 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Goodyear 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,198.30	6,912.45	4,285.85	38.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,700.00	4,030.00	3,670.00	47.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,898.30	10,942.45	7,955.85	42.10
Approved Total (Overridden) (S\$)		8,150.00		
(S\$)	18,898.30	8,150.00	10,748.30	56.87
+ GST 7.00/7.00% (S\$)	1,322.88	570.50	752.38	56.87
Nett Amount (S\$)	20,221.18	8,720.50	11,500.68	56.87
+ Loss of Use (16.0 x S\$80.00/day) (S\$)		1,280.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,002.50		

INSPECTION

Date of Assignment:	30/06/2022		
Date Inspected:	30/06/2022	Inspected At:	Spark Car Care @ Braddell (HQ) 205 BRADDELL RD Singapore 579701
Estimated Period of Repair:	14.0 days		

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 03 Nov 2022)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD6960U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	525.00 FN	*525.00 FN
2	1		*REAR BUMPER RETAINER RH	Distorted	41.00 FN	*41.00 FN
3	1		*REAR BUMPER RETAINER LH	Cracked	41.00 FN	*41.00 FN
4	1		*BUMPER SPONGE	Cracked	102.00 FN	*102.00 FN
5	8		*BUMPER LIP	Necessary	40.00 FN	*40.00 FN
6	2		*REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
7	1		*REAR BUMPER REFLECTOR RH	Serviceable	67.00 FN	*- FN
8	1		*REAR BUMPER REFLECTOR LH	Serviceable	67.00 FN	*- FN
9	1		*REAR END PANEL OUTER	Bent	124.00 FN	*124.00 FN
10	1		*REAR END PANEL INNER	Bent	622.00 FN	*622.00 FN
11	1		*REAR END PANEL TOP GARNISH	Serviceable	124.00 FN	*- FN
12	1		*REAR FLOOR CARPER	Deformed	2,000.00 FN	*1,200.00 FN
13	1		*REAR RH BACK DOOR	Bent	984.00 FN	*984.00 FN
14	1		*RR RH BACK DOOR GLASS	Serviceable	517.00 FN	*- FN
15	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
16	1		*REAR 5 PAX STICKER	Necessary	30.00 FS	*15.00 FS
17	1		*REAR 70KM/H STICKER	Necessary	18.00 FS	*15.00 FS
18	1		*RR RH BACK DOOR VERTICAL RUBBER SEAL	Distorted / Cut	65.00 FN	*65.00 FN
19	1		*RR RH BACK DOOR LOCK TOP	Repair	107.00 FN	*- FN
20	1		*RR RH BACK DOOR LOCK LOWER	Repair	125.00 FN	*- FN
21	1		*RR RH BACK DOOR LOCK LOWER CATCH	Repair	38.00 FN	*- FN
22	1		*RR RH BACK DOOR HINGE TOP	Repair	105.00 FN	*- FN
23	1		*RR RH BACK DOOR HINGE LOWER	Repair	116.00 FN	*- FN
24	1		*RR RH BACK DOOR INNER TRIM BOARD	Serviceable	130.00 FN	*- FN
25	1		*RR LH BACK DOOR	Bent	1,312.00 FN	*1,102.50 FN
26	1		*RR LH BACK DOOR HINGE TOP	Repair	116.00 FN	*- FN
27	1		*RR LH BACK DOOR HINGE LOWER	Repair	116.00 FN	*- FN
28	1		*RR LH BACK DOOR LOWER LOCK CATCH	Jammed	38.00 FN	*38.00 FN
29	1		*RR LH BACK DOOR INNER LOCK TRIMBOARD	Deformed	130.00 FN	*130.00 FN
30	1		*RR LH SIDE PANEL OUTER	Buckled	1,767.00 FN	*1,636.00 FN
31	1		*RR LH SIDE PANEL INNER	Repair	1,463.00 FN	*- FN
32	1		*RR LH SIDE PANEL AIR VENT	Serviceable	75.00 FN	*- FN
33	1		*LH TAILLAMP	Broken	340.00 FN	*340.00 FN
34	1		*RH TAILLAMP	Cracked	340.00 FN	*340.00 FN
35	1		*LH BACK DOOR NUMBER PLATE GARNISH	Serviceable	380.00 FN	*- FN
36	1		*RR NUMBER PLATE W/CASE/LONG/EMBOSS/BLACK NO	Bent	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	12,400.00	7,645.50
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	1,201.70	733.05
Total Parts (\$\$)	11,198.30	6,912.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT WELD LH REAR SIDE PANEL INNER & OUTER ,END PANEL INNER AND OUTER ,JACK STRAIGHTEN ,FLOOR PANEL ,RH REAR SIDE PANEL ,INNER PANEL ,TOP PANEL ,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	2,500.00	2,250.00
2	TO PUTTY ,RESPRAY ON BOTH REAR DOOR ,END PANEL,FLOOR PANEL ,BOTH REAR SIDE PANEL TOP PANEL AND AFFECTED AREAS	New	2,000.00	1,500.00
3	TRANSFER DOOR PARTS TO NEW DOORS	New	300.00	160.00
4	REMOVE INTERIOR UPHOLSTERY TO ASSIST REPAIR AND REFIX	New	150.00	100.00
5	CHECK LIGHTING AND WIRING	New	50.00	20.00
6	TO REDO BODY ART WORK	New	2,700.00	0.00
			Gross Labour Cost (\$\$)	4,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >